

Appendix D

Mystic Area Building Inspection Results

Building Inspection Results

Stonington Building Inspection Results
May to July 2022

OWNER_NAME	HOUSE_NO	STREET	Interior Inspection					No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Detailed SKETCH	Potential Illicit - No Sketch
			Date of Building Inspection (Hart)	Basement Type	Lateral Location	Sump Pump	Additional Drains	Breaker Box / Electric Panel	Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains	Roof Leaders		
VONA MARY T & ELIZABETH CANDACE	10	ALDEN ST	5/17/2022	Basement	SE	NW	No	NE	Yes	No	See Sketch	Yes	No	No	Yes	No
INDIAN KEY LLC	21	BROADWAY AVE														
ARC CBASTNCT001 LLC	23	BROADWAY AVE	6/23/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	Maybe	No	Yes
SHERWOOD ISLAND 21 LLC	25	BROADWAY AVE	6/22/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	Maybe	No	Yes
NEW ENGLAND REAL ESTATES LLC	27	BROADWAY AVE	6/27/2022	Basement	NW	SW	No	West	Yes	No	See Sketch	No	No	No	No	No
Apple Rehab	28	BROADWAY AVE	5/17/2022	Partial Basement	NA	SE Basement	Yard Drain	NW Basement	Yes	Yes	See Sketch	No	No	No	No	No
FITZPATRICK JANE L LU	3	BROADWAY AVE	6/7/2022	Basement	SE	SW	No	NA	Yes	No	See Sketch	No	No	No	No	No
THIRTY BROADWAY LLC	30	BROADWAY AVE	6/16/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
ROOHAH ASSOCIATES III LLC	31	BROADWAY AVE														
G DEVELOPMENT LLC	32	BROADWAY AVE	6/24/2022	Stilts	NA	NA	NA	NA	NA	NA	See Sketch	No	No	No	No	No
MYSTIC FIRE DISTRICT	34	BROADWAY AVE	6/16/2022	Slab on Grade	NA	NA	No	NA	Yes	Yes	See Sketch	No	Yes	No	No	Yes
TRUBIA RAYMOND P & ANDREA Y	6	BROADWAY AVE	6/7/2022	Basement	NW	North & SE	No	South	Yes - rainbarrels		See Sketch	No	No	No	No	No
STANTON JAMES	12	BROADWAY AVE EXT	6/21/2022	Basement	SW	SW and NW	No	NA	Yes	No	See Sketch	No	No	No	No	No
TAMSKY BENJAMIN & ELEANOR R	16	BROADWAY AVE EXT	6/1/2022	Crawl Space	NW	SW	No	NA	Yes	No	See Sketch	No	No	No	No	No
HOLLY MACHINE WORKS LLC	2	BROADWAY AVE EXT	6/16/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
AURETTA MAVIS	24	BROADWAY AVE EXT	6/1/2022	Basement	West	SW	No	NA	Yes	No	See Sketch	No	No	No	No	No
WILLS TIMOTHY BRYAN & TASCA LAUREN J & WILLS LAUREN J	27	BROADWAY AVE EXT	6/23/2022	Basement	West	NW	No	SW	No	No	See Sketch	No	No	No	No	No
FRIEDRICH ROBERT H & MARION A	28	BROADWAY AVE EXT	6/22/2022	Unknown	NA	NA	NA	NA	Yes	No	See Sketch	No	No	No	No	No
JORDAN DORIAN ANKA	29	BROADWAY AVE EXT	6/3/2022	Basement	SW	SE and SW (2 pumps)	No	NA	Yes	No	See Sketch	No	No	No	No	No
MERSHON JON V & MERSHON JON J	30	BROADWAY AVE EXT	6/22/2022	Unknown	NA	NA	NA	NA	Yes	No	See Sketch	NA	NA	No	No	No
FRIEDRICH ROBERT H	4	BROADWAY AVE EXT	6/16/2022	Slab on Grade	NA	No	No	NA	No	No	See Sketch	NA	NA	No	No	No
MURPHY POINT REALTY LLC	7	BROADWAY AVE EXT	5/10/2022	Slab	W towards N	W towards N	No	Multiple	Yes	No	See Sketch	Yes (2)	No	No	Yes	No
PLANETA PROPERTIES	32	CHURCH ST M	6/22/2022	Basement	NW	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
MAYORGA OLIVER & KARI K SHIELDS DAVID S II & DAVID S	33	CHURCH ST M	6/29/2022	Basement	NW	West	No	NA	Yes	No	See Sketch	No	No	Maybe	No	Yes
CODY RICHARD S	34	CHURCH ST M														
PALMA STEPHEN F	36	CHURCH ST M	6/24/2022	Crawl Space	NW	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
FILES LINDA J TRUSTEE	38	CHURCH ST M	6/22/2022	Basement	South	West	No	NA	Yes	No	See Sketch	No	No	No	No	No
TETLOW DAVID W & LOOHRIE JUDITH	40	CHURCH ST M	6/24/2022	Basement	NW	NW	No	NA	Yes	No	See Sketch	No	No	No	No	No
TETLOW DAVID WAYNE & ELAINE B	42	CHURCH ST M	6/23/2022	Basement	NE	No	No	NW	Yes	No	See Sketch	No	No	No	No	No
SCHOMAKER JOSEPH H & SHELLI J	44	CHURCH ST M	6/24/2022	Basement	NW	SW	No	NA	Yes	No	See Sketch	No	No	No	No	No
GILL BRIAN E & SHERRI A STEVENS KEITH J	45	CHURCH ST M														
WINKLER KARL L	46	CHURCH ST M														
COLLER SHONYA A	48	CHURCH ST M														
KOWAL GRETCHEN G & COLLIER SHONYA A	50	CHURCH ST M	7/2/2022	Basement	NE	NE	No	NE	Yes	No	See Sketch	No	No	No	No	No
MURPHY MANAGEMENT LLC	51	CHURCH ST M	5/19/2022	Basement & Slab	Varies	Yes	No	Multiple	Yes	No	See Sketch	Yes	No	No	Yes	No
TYLASKA THEODORE T III	52	CHURCH ST M														
CHAND CHANDRA	54	CHURCH ST M	6/28/2022	Basement	SW	SW	No	SW	Yes	No	See Sketch	No	No	Maybe	No	Yes
PANCIERA M PAMELA	56	CHURCH ST M														
MYSTIC DRAWBRIDGE HOLDINGS I LLC	11	COTTRELL ST	5/11/2022	Slab on Grade	Northern side of building		No	NA	Yes	No	Parking lot on East side	No	No	No	No	No
MILKIE DAVID R & SHERRI LYNN	21	COTTRELL ST														
MYSTIC FIRE DISTRICT	25	COTTRELL ST	5/31/2022	Basement	North	Yes	No	NA	Yes	No	NA	No	No	No	No	No
WHALEYS INN 9 COTTRELL LLC	9	COTTRELL ST	5/11/2022	Slab on grade	NE	No	No	NA	No	No	See Sketch	No	No	No	No	No
MYSTIC FIRE DISTRICT		COTTRELL ST	5/31/2022	Multiple - slab, crawl, basement	Varies	Yes (#27)	No	NE (#27)	Yes	No	See Sketch	Yes (#27)	No	No	Yes (#27)	No
PASIEKA SANDRA L & DAVID A	12	DENISON AVE M														
CITRON MARILYN TRUSTEE	14	DENISON AVE M	6/28/2022	Basement	SE	NW	No	NA	Yes	Yes	See Sketch	Yes	No	Maybe	Yes	Yes
BUNGER ROBERT E & ANDREA D	18	DENISON AVE M	6/27/2022	Basement	NW	North	No	NW	Yes	No	See Sketch	Yes	No	No	Yes	No

Stonington Building Inspection Results
May to July 2022

OWNER_NAME	HOUSE_NO	STREET	Interior Inspection					No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Detailed SKETCH	Potential Illicit - No Sketch
			Date of Building Inspection (Hart)	Basement Type	Lateral Location	Sump Pump	Additional Drains		Breaker Box / Electric Panel	Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains		
PAVONE PHILIP F & MCLELLAND CINDY J	20	DENISON AVE M	7/2/2022	Basement	NW	NW	No	West	Yes	No	See Sketch	No	No	No	No	No
TERRELL DANIEL R	21	DENISON AVE M	6/27/2022	Basement	South	No	No	NA	Yes	No	See Sketch	No	No	No	No	Yes
ONEAL AMY & HINE JASON R	23	DENISON AVE M	6/21/2022	Basement	NE	NW	No	NA	Yes	No	See Sketch	No	No	No	No	No
RANCK ROBERT D & SHAFER KIM M	24	DENISON AVE M														
C & M CHUDY LLC	25	DENISON AVE M	6/24/2022	Basement	NW	NE	No	SE	Yes	No	See Sketch	No	No	No	No	No
SALERNO NICHOLAS R & JUDITH A TRUSTEES	26	DENISON AVE M	5/18/2022	Basement	NE side	West	Yard Drains	North	Yes	Yes	See Sketch	No	No	No	No	No
JESSE STEVEN L & VICKI L	30	DENISON AVE M														
MACRIS ATHOS C & MARGARET	36	DENISON AVE M	6/23/2022	Unknown	NW	NA	No	NA	Yes	No	See Sketch	NA	No	No	No	Yes
DEISHER BRUCE T+VIRGINIA K	39	DENISON AVE M	6/23/2022	Basement	North	SW	No	NA	Yes	No	See Sketch	Yes	No	No	Yes	No
OCEAN BREEZELAND COMPANY LLC	4	DENISON AVE M														
MACRIS CONSTANTINE A & DEANNA M	40	DENISON AVE M	6/23/2022	Basement	SE	No	No	West	Yes	No	See Sketch	No	No	No	No	No
RAMSDELL ROBERT T	41	DENISON AVE M	6/23/2022	Basement	West	NE	No	NE	Yes	No	See Sketch	No	No	No	No	No
KLISE MARGARET M	42	DENISON AVE M	6/23/2022	Basement	SW	SW	No	NA	Yes	No	See Sketch	No	No	No	No	No
LAFFIN ANTON E & SCHOLL JESSICA E	43	DENISON AVE M	6/4/2022	Basement	NW	SW	No	NE	Yes	No	See Sketch	No	No	Maybe	No	Maybe
SCHRAGE DANIEL & LARA	44	DENISON AVE M	6/23/2022	Basement	West	No	No	East	Yes	No	See Sketch	No	No	Maybe	No	Yes
CROUCHER ROBERT E & JANE F	48	DENISON AVE M	6/23/2022	Basement	North	NW	Yes	NA	Yes	Yes	See Sketch	No	No	No	No	No
GAZLAY ROBERT L & PEGGY J	54	DENISON AVE M	6/24/2022	Basement	North	SW	No	SW	Yes	No	See Sketch	No	No	No	No	No
SHORT JAMES K II	8	DENISON AVE M														
WHALERS INN REL LC	20	E MAIN ST	5/11/2022	Slab on Grade & Basement	See sketch - varies	Yes (3)	No	See sketch	Yes	No	Parking lot South of Main Inn	No	No	No	No	No
MYSTIC 22 LLC	22	E MAIN ST	5/11/2022	Basement	NE side	Yes	No	SE of basement	Yes	No	Parking lot - South side	Yes	No	No	Yes	Yes
MOOGIE LLC	24	E MAIN ST	6/27/2022	Slab on Grade	NA	NA	NA	NA	Yes	NA	See Sketch	NA	NA	No	No	Yes
MYSTIC PET SHOP LLC	28	E MAIN ST	5/11/2022	Slab on grade	NE side	No	No	NW room, eastern wall of room	Yes (5) to ground	No	Parking lot	No	No	No	No	No
SOUTHERN NEW ENGLAND TELEPHONE COMPANY	30	E MAIN ST														
ST PATRICKS CHURCH	31	E MAIN ST	6/14/2022	Basement	NE	NE	No	SW	Yes	No	See Sketch	No	No	No	No	No
ST PATRICKS CHURCH CORP	32	E MAIN ST	6/14/2022	Basement	SE	East	No	NA	Yes	No	See Sketch	No	No	No	No	No
MYSTIC FOOD N MORE LLC	34	E MAIN ST	6/15/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
THIRTY EIGHT LLC	38	E MAIN ST	6/15/2022	Basement	South of original build	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
BLCR HOLDINGS LLC	39	E MAIN ST	6/21/2022	Crawl Space	SW	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
SINNETT FRANK L & BARBARA A	4	E MAIN ST	5/11/2022	Slab on Grade	Southern side of building	No	NA	ground floor, curtain wall on southern side of building.	3 leaders SW, SE, West discharge to ground.	NA	Mystic River to West, oil tank to S.	No	No	No	No	No
CONRY LLC	41	E MAIN ST	6/15/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
MYSTIC CONGREGATIONAL	45	E MAIN ST	5/18/2022	Basement, Slab, Crawl	Parish (W), Moran (NE)	Yes	No	See sketch	Yes	No	See Sketch	No	No	No	No	No
TROUTMAN MATTHEW D & MERL L	51	E MAIN ST														
REDDICK GORDON B & DENISE E	53	E MAIN ST														
CONLON JEFFREY R & JENNIFER A	54	E MAIN ST	6/21/2022	Basement	South	3 (center of northern section)	No	NA	Yes	No	See Sketch	No	No	No	No	No
JASTREMSKI DOUGLAS J & ROBERT J & JOY C	55	E MAIN ST														
LEWIS MICHAEL	56	E MAIN ST	7/2/2022	Basement	NW	NW	No	NW	Yes	No	See	No	No	No	No	No
LEWIS MICHAEL	58	E MAIN ST	7/2/2022	Basement	NW	SE	No	NA	Yes	No	See	No	No	No	No	No
MARKU PETRIT	57	E MAIN ST														
GINNETTI DANIEL R	59	E MAIN ST	6/21/2022	Basement	NE	No	No	NA	Yes	No	See Sketch	No	No	No	No	No
BROBERG RICHARD H & TOMASINO SUSAN F	60	E MAIN ST														
WATERS KRISTOPHER & HEATHER	61	E MAIN ST	5/10/2022	Basement	SW	No	No	North	Yes	No	See Sketch	No	No	Yes	No	Yes
SVED LUCY MICHELLE & DEPASCALE MICHAEL	62	E MAIN ST														

Stonington Building Inspection Results
May to July 2022

OWNER NAME	HOUSE_NO	STREET	Date of Building Inspection (Hart)	Interior Inspection					No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Detailed SKETCH	Potential Illicit - No Sketch
				Basement Type	Lateral Location	Sump Pump	Additional Drains	Breaker Box / Electric Panel		Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains	Roof Leaders		
FALARDEAU CLAUDE J TERWILLIGER ROSS G & DENNIS T FALARDEAU CLAUDE J TAMSKY BENJAMIN & ELEANOR R	0	EDGEMONT ST	6/29/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	11	EDGEMONT ST	6/1/2022	Basement (ground level)	NE	North	No	NE	Yes	No	See Sketch	Yes	No	No	No	No	
	14	EDGEMONT ST	6/29/2022	Crawl Space	NW (main)	No	No	NA	No	No	See Sketch	No	No	No	No	No	
	15	EDGEMONT ST	6/1/2022	Slab	NA	No	No	NA	Yes	No	See Sketch	No	No	No	Yes	Yes	
	5	EDGEMONT ST	6/1/2022	Garage Level	NE	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
BARNHART JEFFREY G & ANNE M	7-9	EDGEMONT ST	4/30/2022	Slab on Grade	Vertical exterior SW (7) Interior NE corner (9)	No	NA	NA	3 leaders discharge to ground	NA	N side neighbor fence on 6" maple E corner	NA	NA	NA	No	No	
	1-3	HALEY ST	Parking lot	Basement	SE	SE	No	NW	Yes	No	See Sketch	Yes	No	No	No	No	
WHALENS INN RELL C LAVALLEY WILLIAM J 4 HALEY STREET LLC 5 HALEY STREET LLC DONNELLY PAUL BLU & JUSSILA LORITA F LU VANDALE SCOTT D WHEELER JAMES T & PATRICIA C OLD MYSTIC LLC BOISSEVAIN ELAINE M TRUSTEE MARTLEY JENNIFER L & CARPENTER SUSAN M WOLCIN NOELLE C SARTOR CLARE & PAUL GIBBS PAMELA CRAIMER & JAMES	2	HALEY ST	6/23/2022	Basement	SE	SE	No	NW	Yes	No	See Sketch	No	No	No	No	No	
	4	HALEY ST	6/15/2022	Basement	NE	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	No
	5	HALEY ST	6/27/2022	Crawl Space	North	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	No
	6	HALEY ST	5/31/2022	Basement	SE	No	No	SE	Yes	No	See Sketch	No	No	Maybe	No	Yes	
	7	HALEY ST															
	9	HALEY ST	5/17/2022	Basement	West	SE	No	NE	Yes	No	See Sketch	Yes	No	No	Yes	No	
	6	HALEYS WAY	6/9/2022	Crawl Space	SW	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	40	HOLMES ST	5/17/2022	Basement	NE side	Western Center	Yes	Unknown	Yes	Yes	See Sketch	No	No	No	No	No	
	10	JACKSON AVE	6/14/2022	Basement	NW	NW	No	NA	Yes	Yes	No	See Sketch	No	No	No	No	No
	11	JACKSON AVE															
SARTOR CLARE & PAUL GIBBS PAMELA CRAIMER & JAMES SPEGEL CARL E GENERATION 4 LLC SMITH DAVID B & ROBIN R MAREKA KARLY A & MATTHEW M DURANT JOAN K TRUSTEE STANLESS PROPERTIES LLC ROCCON KAREN O & DUTTON RONALD A ROSEN GAIL MLLS KATINA S URBANEX MATTHEW GUSTAFSON ANN C EMERALD SHIELD PROPERTIES LLC REBICH DAVID A & LILLI M HEAL TAYLOR J & MACKENZIE D JOHNSON DIANE L DUNNINGTON GEORGE B JR TRUSTEE VEGAS LUIS & IRENE AHEARN ROBERT E & HELEN P 2 LINCOLN AVE LLC LECORNET ALAN & KIMBERLY KAIN LOIS H & LOIS HRESCHAK WAYNE C MORRISON REVOCABLE TRUST ANDERSEN CURT & LAILA TEN MAIN STREET LLC CALLANISH LLC ROWE SARAH E A & SHEEDY STEPHEN CHARLES CALLANISH LLC STOUCH EVEANNE E	12	JACKSON AVE	6/15/2022	Basement	SE	West	No	NA	No	No	See Sketch	No	No	No	No	No	
	14	JACKSON AVE	6/15/2022	Basement	South	No	No	NA	No	No	See Sketch	No	No	No	No	No	No
	15	JACKSON AVE															
	19	JACKSON AVE	6/15/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	2	JACKSON AVE	5/10/2022	Basement	NE	N	No	NE	Yes	No	See Sketch	No	No	Yes	No	No	
	20	JACKSON AVE	6/15/2022	Basement	North	South Central	No	NE	Yes	No	See Sketch	No	No	No	No	No	
	22	JACKSON AVE	6/15/2022	Basement	West	1-West, 1-East	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	23	JACKSON AVE	6/29/2022	Slab on Grade	NA	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	24	JACKSON AVE	6/22/2022	Basement	SW	SW (2)	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	3	JACKSON AVE	6/22/2022	Unknown	East	NA	NA	NA	Yes	No	See Sketch	NA	NA	No	No	No	
	4	JACKSON AVE															
	5	JACKSON AVE	6/14/2022	Basement	NW	South	No	West	Yes	No	See Sketch	No	No	No	No	No	
	6	JACKSON AVE	5/17/2022	Crawl Space	SW	NW	No	Unknown	Yes	No	See Sketch	Yes	No	Yes	Yes	Yes	
	7	JACKSON AVE	6/16/2022	Crawl Space	SW	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	8	JACKSON AVE	6/9/2022	Crawl Space	NE	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
	9	JACKSON AVE															
	11	JEROME AVE	6/1/2022	Basement	South	SE	No	NW	Yes	No	See Sketch	No	No	No	No	No	
	12	JEROME AVE	6/1/2022	Basement/Crawl Space	NE	No	No	NA	NA	No	No	See Sketch	No	No	No	No	No
4	JEROME AVE	6/7/2022	Basement	NE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No	No	
18	LINCOLN AVE M																
2	LINCOLN AVE M	5/19/2022	Partial Basement	East	Yes	No	No	South under apartments	Yes	No	See Sketch	Yes	No	No	Yes	No	
23	LINCOLN AVE M																
24	LINCOLN AVE M	6/24/2022	Basement	SE	SW	No	No	South	Yes	No	See Sketch	No	No	No	No	No	
5	LINCOLN AVE M	6/29/2022	Basement	Wesr	SE	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
6	LINCOLN AVE M	6/16/2022	Basement	East	NW	No	No	NW	Yes	No	See Sketch	No	No	No	No	No	
10	MAIN ST OM	6/9/2022	Slab on grade	North	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No	No	
11	MAIN ST OM	6/7/2022	Slab on grade	NA	No	NA	NA	NA	Yes	No	See Sketch	No	No	No	No	No	
16	MAIN ST OM	6/7/2022	Crawl Space - inaccessible	South	No	No	No	NA	Yes	No	See Sketch	No	No	No	No	No	
18	MAIN ST OM	7/2/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	NA	NA	Yes	
2	MAIN ST OM	7/2/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	NA	NA	Yes	

Stonington Building Inspection Results May to July 2022

OWNER_NAME	HOUSE_NO	STREET	Date of Building Inspection (Hart)	Interior Inspection				No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Detailed SKETCH	Potential Illicit - No Sketch
				Basement Type	Lateral Location	Sump Pump	Additional Drains		Breaker Box / Electric Panel	Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains	Roof Leaders	
OGRADY MATHEW	20	MAIN ST OM	6/7/2022	Basement	SE	SE	No	NA	NA	Yes	No	See Sketch	Yes	No	No	Yes
HARING MARIA V	24	MAIN ST OM	6/28/2022	Basement	North Central	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
PEGLOW STEPHEN E & SUSAN D	26	MAIN ST OM	6/27/2022	Basement	East	No	No	West	West	Yes	No	See Sketch	No	No	No	No
29 MAIN LLC	29	MAIN ST OM	6/8/2022	Slab on grade	North	No	No	NA	NA	No	No	See Sketch	No	No	No	No
MYSTIC ALCHEMY LLC	3	MAIN ST OM	7/12/2022	Basement	NW	No	No	North	North	No	No	See Sketch	No	No	No	No
PAGE JESSICA R	30	MAIN ST OM	6/28/2022	Crawl Space	SW	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
RUSSO JERIA	32	MAIN ST OM	7/2/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	NA	Yes
ROZZI-LOCHS JESSICA	33	MAIN ST OM	6/7/2022	Basement	East	East	No	NA	NA	Yes	No	See Sketch	No	No	No	No
HOWARD RALPH K JR	34	MAIN ST OM	6/23/2022	Crawl Space	East	South	No	NA	NA	Yes	No	See Sketch	No	No	No	No
MINER HAROLD W & ANNETTE M TRUSTEES	35	MAIN ST OM	7/2/2022	NA	NA	NA	NA	NA	NA	No	NA	NA	NA	NA	NA	Yes
INDIAN & COLONIAL RESEARCH CENTER INC	39	MAIN ST OM	5/10/2022	Unknown - most likely slab	North	Unknown	No	Unknown	Unknown	Yes	No	See Sketch	No	No	No	No
ZOBEL MELISSA F	4	MAIN ST OM	7/2/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	NA	Yes
BUDDING ANNE E & ORZECZ JOHN D	40	MAIN ST OM	5/10/2022	Crawl Space	South	No	No	SE	SE	Yes	No	See Sketch	No	No	No	No
PAGE MICHAEL & OHERIL	41	MAIN ST OM	5/10/2022	Unknown - most likely slab	North	Unknown	No	Unknown	Unknown	Yes	No	See Sketch	No	No	No	No
OLD MYSTIC M E CHURCH	44	MAIN ST OM	6/27/2022	NA	South	NA	NA	NA	NA	Yes	No	See Sketch	NA	No	No	Yes
DELARA ADYIN TRUSTEE	46-48	MAIN ST OM	6/9/2022	Basement	SW	South (2)	Yes	NA	NA	Yes	Yes	See Sketch	No	No	No	No
47 MAIN STREET OLD MYSTIC LLC	47	MAIN ST OM	7/2/2022	Slab on Grade	NA	No	No	NA	NA	Yes	No	See Sketch	No	No	NO	Yes
LOCHIATTO ALBERT A & LAWRENCE LOS J TRUSTEES	49-51	MAIN ST OM	6/9/2022	Basement	NE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
BED D F TRUSTEE	52	MAIN ST OM	6/9/2022	Basement	South	Yes	Yes	NA	NA	Yes	Yes	See Sketch	No	No	No	No
HANKS MILDRED L	53	MAIN ST OM	6/8/2022	Crawl Space	SE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
SMITH HALEY L	57	MAIN ST OM	6/9/2022	Basement	NE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
HABERMAN ROBERT COCONIE LYNN	58	MAIN ST OM	6/8/2022	Basement	NW	West	No	NA	NA	Yes	No	See Sketch	No	No	No	No
MICHELSON RICHARD S & RACHELLE B	62	MAIN ST OM	7/2/2022	Basement	SW	SE	No	NA	NA	Yes	No	See Sketch	No	No	No	No
PARK JASON D & GARY	63	MAIN ST OM	6/9/2022	Crawl Space	SE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
OLD MYSTIC ME CHURCH	68	MAIN ST OM	7/6/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	No	Yes
BERRYHILL DEBORAH	6	MAIN ST OM	6/9/2022	Crawl Space	SW	SW	No	NA	NA	Yes	No	See Sketch	No	No	No	No
MERCER ROBERT T	8	MAIN ST OM	6/9/2022	Crawl Space	South	No	No	NA	NA	No	No	See Sketch	No	No	No	No
ANSEL WILLITS D & HANNELI V TRUSTEES	4	MILL ST	6/3/2022	Basement	SW	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
6	MILL ST			Basement	SW	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
8	MILL ST			Basement	NE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
COKER JAMES L V TRUSTEE	8	MILL ST	6/3/2022	Basement	NE	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
CHUNG WOON WAH YU	13	MISTUXET AVE														
FINNIAGAN STEPHEN	20	MISTUXET AVE	5/10/2022	Basement	West	W	No	NW	NW	Yes	No	See Sketch	No	No	No	No
WAGENER JULIANE E TRUSTEE	31	MISTUXET AVE	5/18/2022	Basement	SW	SE	No	SE	SE	Yes	No	See Sketch	No	No	Yes	No
DWYER LESLIE A	13	N STONINGTON RD	6/9/2022	Basement	NE	SE and SW (2 pumps)	No	NA	NA	Yes	No	See Sketch	No	No	No	No
OLD MYSTIC FIRE DISTRICT	21	N STONINGTON RD	6/16/2022	Slab on Grade	South	No	No	NE	NE	Yes	Yes	See Sketch	No	No	Maybe	Yes
BUTLER JB & TILLMAN PALMER L JR & JULIA LYONS JOSHUA C & LINDSTROM LINNEA MUSTDO LLC	25	N STONINGTON RD	6/9/2022	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
1437	PEQUOT TR		6/21/2022	Basement	SW	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
1440	PEQUOT TR		7/6/2022	NA	NA	NA	NA	NA	NA	Yes	NA	NA	NA	NA	No	Yes
VARGAS ESTEBAN	1443	PEQUOT TR	6/7/2022	Basement	NE	No	Floor drain in garage	NA	NA	Yes	No	See Sketch	No	No	No	Yes
PHILLIPS BONNIE P	1444	PEQUOT TR	6/14/2022	Basement	NE	SE	Yes	East	East	Yes	Yes	See Sketch	No	No	No	Yes
DEWALT STACY & JAMES	1446	PEQUOT TR	6/28/2022	Basement	NW	No	No	NA	NA	Yes	No	See Sketch	No	No	Maybe	Yes
MENNITT FRANK S & MILLER SANDRA J	10	REYNOLDS HILL RD	6/9/2022	Basement	North	No	No	NA	NA	Yes	No	See Sketch	No	No	No	No
MMI CT HOLDINGS LLC	3	REYNOLDS HILL RD														
DESKUS ROBERT A & PATRICIA A	4	REYNOLDS HILL RD														
ARRUDA CRAIG T & JODIE R	7	REYNOLDS HILL RD														
ORRIS JONATHAN K & JOAN L	8	REYNOLDS HILL RD	6/29/2022	Basement	NE	SW	No	NA	NA	Yes	No	See Sketch	No	No	No	No
J-HB AND ASSOCIATES LLC	12	ROOSEVELT AVE	5/11/2022	Slab	North	South	No	Multiple	Multiple	Yes	No	See Sketch	Yes	No	Yes	No
BRUNO ROBERT & SEARS ROBERT N	17	ROOSEVELT AVE														

Stonington Building Inspection Results May to July 2022

OWNER_NAME	HOUSE_NO	STREET	Date of Building Inspection (Hart)	Interior Inspection					No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Potential Illicit - No Sketch
				Basement Type	Lateral Location	Sump Pump	Additional Drains	Breaker Box / Electric Panel		Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains	Roof Leaders	
KS REAL ESTATE DEVELOPMENT LLC	19	ROOSEVELT AVE														
NATL RAILROAD PASSENGER CORP	2	ROOSEVELT AVE	5/31/22 & 6/1/22	Crawl Space	NW	NW	No	NA		Yes	No	See Sketch	No	No	Maybe	Yes
Noble Smokehouse	4	ROOSEVELT AVE	5/31/22 & 6/3/22	Crawl Space	NE	NE	No	NA		Yes	No	See Sketch	Yes	No	No	No
TYLASKA THEODORE T TRUSTEE	21	ROOSEVELT AVE														
LONGINIDIS REALTY LLC	25	ROOSEVELT AVE	6/24/2022	Slab on Grade	NE & SE (2)	South Central	Yes (internal roof)	NA		No	No	See Sketch	No	No	No	No
PETROLEUM MARKETING INVESTMENT GROUP LLC	3	ROOSEVELT AVE	6/22/2022	Slab on Grade	NA	No	No	NA		Yes	No	See Sketch	No	No	No	Yes
MYSTIC LAND CO LLC	7	ROOSEVELT AVE	6/24/2022	Slab on Grade	NE	NA	No	NA		Yes	No	See Sketch	No	No	No	No
BALESTRACCI JEFFREYA JR & MADELINE F	13	SMITH ST OM	6/8/2022	Crawl Space	South	No	No	NA		NA	No	See Sketch	No	No	No	No
VANDAL PAUL J & SALLY BOVARNICK MITCHELL A	4	SMITH ST OM	7/2/2022	Basement	East	NE	No	NE		Yes	No	See Sketch	No	No	Maybe	Yes
	7	SMITH ST OM	7/2/2022	NA	NA	NA	NA	NA	1	Yes	NA	NA	NA	NA	NA	Yes
REGAN DENNIS W	1	SOLOM AVE	6/3/2022	Basement / Crawl Space access	NW	North	No	No		Yes	No	See Sketch	No	No	No	No
SECRETARY OF VETERANS AFFAIRS	12	SOLOM AVE	7/2/2022	NA	NA	NA	NA	NA	1	Yes	NA	NA	NA	NA	NA	Yes
GOWEN DANIEL	16	SOLOM AVE	7/2/2022	NA	NA	NA	NA	NA	1	Yes	NA	NA	NA	NA	NA	Yes
TYLER TANYA & TANYA TRUSTEE	17	SOLOM AVE	6/3/2022	Basement	South	SE	No	SE		Yes	No	See Sketch	No	No	No	No
	18	STAFFORD ST	5/31/2022	Crawl Space / Slab	NW	No	No	NA		Yes	No	See Sketch	No	No	No	No
MUMRO-DELOITTO PAIGE & MUMRO JUDITH	18A	STAFFORD ST	6/3/2022	Basement	SE	South	No	NA		No	No	See Sketch	No	No	No	No
MYSTIC SHIPYARD LLC	2	STAFFORD ST	6/8/2022	Slab on grade	South	No	No	NA		Yes	No	See Sketch	No	No	No	No
	21	STAFFORD ST	7/2/2022	Basement	SW	NE	No	NA		No	No	See Sketch	No	No	No	No
RAU DONALD & CRISTY	8	STAFFORD ST	5/11/2022	Crawl Space	NE side of building	Yes	No	Unknown		Yes	No		No	No	No	No
WILSON CONSTANCE A & SHERIA CO-TRUSTEES	3	STANTON PL														
COMINS FREDERIC M JR & M ROBIN J	5	STANTON PL	6/14/2022	Basement	North	SE	Yes	East		Yes	Yes	No	No	No	No	No
PETERSEN ROBERT M & ANNE MARIE	1	SUMMIT ST M	7/6/2022	Basement	West	NE	Yes	NA		Yes	Yes	See Sketch	No	No	No	No
TURNER HOWARD M	3	SUMMIT ST M	5/18/2022	Crawl Space	NE side of building	No	No	NA		No	No	See Sketch	No	No	Yes	Yes
PLATT DARLENE M	5	SUMMIT ST M	6/21/2022	Basement	NW	SW	No	SE		Yes	No	See Sketch	Yes	No	No	No
HMD HOLDINGS LLC	8	SUMMIT ST M	6/8/2022	NA	NW	NA	NA	NA		NA	NA	NA	NA	NA	NA	NA
NORRIS THOMAS J & TERESA M	1	SYLVIA AVE	6/1/2022	Basement (dirt floor)	SW	Yes	No	NA		Yes	No	See Sketch	No	No	No	No
LOCKWOOD NANCY L	3	SYLVIA AVE	6/8/2022	Basement	SW	No	No	NA		Yes	No	See Sketch	No	No	No	No
CHURCH BETTY ESTATE & DONALD F	5	SYLVIA AVE	6/1/2022	Basement	NW	SE	No	NW		No	No	See Sketch	No	No	No	No
CHURCH DONALD F & BETTY T ESTATE	7	SYLVIA AVE	6/8/2022	Basement	SW	SE	No	NW		No	No	See Sketch	No	No	No	No
NOANK SHIPYARD INC	10	WASHINGTON STM	6/22/2022	See 4												
DONAHUE ROBERTA J	11	WASHINGTON STM		Washington												
BARRER SPIROS	15	WASHINGTON STM	6/14/2022	Basement	NE	South	No	West		Yes	No	See Sketch	No	No	No	No
HANNON ROBERT F & KATHRYN M	17	WASHINGTON STM														
STEBBINS EDWARD L	28	WASHINGTON STM	6/29/2022	NA	NA	NA	NA	NA		Yes	No	See Sketch	NA	NA	No	Yes
TAPLIN CULLEN MICHAEL	30	WASHINGTON STM	6/29/2022	Basement	NE	NE & SE (2)	No	NE		Yes	No	See Sketch	No	No	No	No
SHEA KEVIN M	32	WASHINGTON STM														
HARTLEY MELANIE A & WILLIAM P	34	WASHINGTON STM	6/21/2022	Basement	NE	SE	No	East		Yes	No	See Sketch	No	No	Maybe	Yes
MYSTIC REAL ESTATE HOLDINGS LLC	35	WASHINGTON STM	6/16/2022	Crawl Space	SE	No	Yes	NA		Yes	Yes	See Sketch	No	No	No	Yes
ROBERT L HARTLEY INTER VIVOS TRUST U/A/D 3/18/2018	36	WASHINGTON STM	6/16/2022	Basement	NE	Yes	No	NW		Yes	No	See Sketch	Yes	No	No	Yes
NOANK SHIPYARD INC	4	WASHINGTON STM	6/22/2022	Basement	NW	East	No	NA		No	No	See Sketch	No	No	No	No
NOANK SHIPYARD INC	4	WASHINGTON STM	6/22/2022	Slab	North	Slab	No	NA		No	No	See Sketch	No	No	No	No
NOANK SHIPYARD INC	4	WASHINGTON STM	6/22/2022	Stilts	NE	No	No	NA		Yes	No	See Sketch	No	No	No	No
MYSTIC JUNCTION LLC	40-44	WASHINGTON STM														
PMIG PROPERTIES LLC	48	WASHINGTON STM														

Stonington Building Inspection Results May to July 2022

OWNER_NAME			HOUSE_NO	STREET	Interior Inspection						No Internal Inspection	Exterior Inspection			Identification of Illicit Connections			Detailed SKETCH	Potential Illicit - No Sketch
					Date of Building Inspection (Hart)	Basement Type	Lateral Location	Sump Pump	Additional Drains	Breaker Box / Electric Panel		Roof Leaders	Yard Drains	Surface Features	Sump Pump	Drains	Roof Leaders		
COAKER KRISTIN & HERRING EDMOND D			51	WASHINGTON ST M	6/21/2022	Basement	SE	West	No	SE		Yes	No	See Sketch	Yes	No	Yes	Yes	
CRUZ ROBERTO & MICHELLE KEMP KERRI			52	WASHINGTON ST M	6/21/2022	Basement	SE	No	No	NA		Yes	No	See Sketch	No	No	No	No	
JOSEPH GWEN ANN MALIK KALIM			54	WASHINGTON ST M	5/19/2022	Basement	SW	Yes	NA	SE		Yes	No	See Sketch	No	No	No	No	
BUONOCORE ANN M & ANNE M & TOULA			56	WASHINGTON ST M	5/17/2022	Basement	SW	SW	No	West		Yes	No	See Sketch	Yes	No	Yes	No	
BUONOCORE ANN M & TOULA			58	WASHINGTON ST M	5/17/2022	Slab (Garage level)	West	West	No			Yes	No	See Sketch	Yes	No	Yes	Yes	
ODONNELL WILLIAM F JR			60	WASHINGTON ST M	5/19/2022	Basement	NA	Yes	No	NA		Yes	No	See Sketch	No	No	No	No	
CANDELORO GERARD J			62	WASHINGTON ST M	5/11/2022	Basement	NE	South Central	No	N		Yes	No	See Sketch	No	No	No	No	
VAIL SALLY M & DONALD E			64	WASHINGTON ST M	6/27/2022	Basement	SE	No	No	NA		Yes	No	See Sketch	No	No	No	No	
KANE WILLIAM A III & SUSAN A			165	WHITEHALL AVE	6/28/2022	Basement	SE	No	No	NA		Yes	No	See Sketch	No	No	No	No	
FAIRBAIN GEOFFREY & RONALD			175	WHITEHALL AVE	6/3/2022	Garage Level	South	No	No	NA		No	No	See Sketch	No	No	No	No	
BOWERS RUTH G TRUSTEE OF THE RUTH G BOWERS REVOCABLE TRUST			187	WHITEHALL AVE	6/14/2022	NA	NA	NA	NA	NA		NA	NA	NA	NA	NA	NA	NA	
GILMAN HADLEY R			195	WHITEHALL AVE	6/29/2022	Basement	SW	No	No	SE		Yes	No	See Sketch	No	No	No	No	
NERI GIOVANNI & DELARM- NERI ADELE JEANNE			196	WHITEHALL AVE	6/28/2022	Basement	NE	No	No	SW		Yes	Yes	See Sketch	No	No	Maybe	No	
BIALEK ELIZABETH & DICOCO RONALD			199	WHITEHALL AVE	5/10/2022	Basement	West	No	No	S		Yes	No	See Sketch	No	No	No	No	
EMERY ROBERT W & MELANIE T			201	WHITEHALL AVE	6/3/2022	Basement	SE	No	No	NA		Yes	No	See Sketch	No	No	No	No	
OGRADY MATHEW P & LLOYD- OGRADY JORDAN			207	WHITEHALL AVE	7/2/2022	NA	NA	NA	NA	NA	1	Yes	NA	NA	NA	NA	NA	Yes	
GUILLE PETER JR			2	WILLIAMS AVE	5/31/2022	Basement	North	SE	No	NA		Yes	No	See Sketch	Yes	No	No	No	
OCEAN BREEZE LAND COMPANY LLC			9	WILLIAMS AVE															
LEBOVITZ KEVIN & GRASS CAROL			31	WILLOW ST	6/27/2022	Finished basement	East	No	No	NA		Yes	No	See Sketch	No	No	No	Yes	
MYSTIC 22 LLC			32	WILLOW ST	5/11/2022	Basement	SE	SE	No	SE		No	No	See Sketch	Yes	No	No	No	
COX GLEN H III & LYNN K TRUSTEES			35	WILLOW ST	6/9/2022	Crawl Space	NE	North	No	NA		Yes	No	See Sketch	Yes	No	Yes	No	
CHARLES MALLORY COTTAGE LLC			37	WILLOW ST	6/15/2022	Crawl Space	North	SE	No	NA		No	No	See Sketch	Yes	No	Yes	No	
BARRES SPYROS			41	WILLOW ST	6/14/2022	Basement	South	NE	No	West		Yes	No	See Sketch	No	No	No	No	
CROWLEY PHILIP J			43	WILLOW ST															
BC PROPERTY HOLDINGS LLC			55	WILLOW ST	6/24/2022	Basement	NW	SE	No	NA		Yes	No	See Sketch	No	No	No	No	
60 WILLOW STREET LLC			60	WILLOW ST	6/28/2022	Crawl Space	NE	No	No	NA		Yes	No	See Sketch	No	No	No	No	

Detailed Sketches

Detail Sketches


List of Addresses

1. 2 Lincoln Avenue
2. 2 Williams Avenue
3. 4 Roosevelt Street
4. 5 Summit Street
5. 6 Jackson Avenue
6. 7 Broadway Avenue Extension
7. 9 Haley Street
8. 10 Alden Street
9. 12 Roosevelt Avenue
10. 14 Denison Avenue
11. 15 Edgemont Street
12. 18 Denison Avenue
13. 20 Main Street OM
14. 22 East Main Street
15. 27 Cottrell Street
16. 32 Willow Street
17. 35 Willow Street
18. 36 Washington Street
19. 37 Willow Street
20. 39 Denison Avenue
21. 51 Church Street
22. 51 Washington Street
23. 56 Washington Street
24. 58 Washington Street

Hart Consults, LLC
05-001

Stonington SSES

2 Lincoln Ave
May 2022.
Residential + Commercial



2ft per square

2 Lincoln Ave.
Residential + Commercial
Basement level


Roosevelt St.

Hart Consults, LLC
05-001

Stonington SSES

2 Williams Ave

May 2022
Commercial
Berkshire Hathaway



2 Williams Avenue

Commercial Building
Berkshire Hathaway Realty



Basement level

2 ft per square

Hart Consults, LLC
05-001

Stonington SSES

4 Roosevelt St
June 2022
Noble Smokehouse
Restaurant



Roosevelt Street

sewer lateral
no dimensions
confined space
significant odor.


4 Roosevelt Street
Noble Smokehouse

2 ft. per square.

Hart Consults, LLC
05-001

Stonington SSES

5 Summit Street
June 2022
Residential




5 Summit Street
Residential Building

2ft per square

Hart Consults, LLC
05-001

Stonington SSES

6 Jackson Ave
May 2022




6 Jackson Avenue
Residential

Hart Consults, LLC
05-001

Stonington SSES
Broadway Ave Ext

7 Broadway Ave Ext
May 2022
Commercial/Industrial
Acme Wiring




10 ft. per square

Hart Consults, LLC
05-001

Stonington SSES

9 Haley St.
May 2022
Residential



Haley Street

9 Haley Street
Residential Building


Basement level

2ft. per square

HartConsults, LLC
05-001

Stonington SSES
Alden St.


10 Alden St.
May 2022
Residential



Hart Consults, LLC
05-001

Stonington SSES

12 Roosevelt St.
May 2022
Commercial
Packer Building



12 Roosevelt Street
Commercial Building
The Packer Building
Crawl Space.


10 ft. per square

Hart Consults, LLC
05-001

Stonington 3SES

14 Denison Ave.
June 2022
Residential

N



Oil tank located under stairs to basement.

Sump pump in basement floor with hatch.

Sump pump pipe encased in concrete and comes out of floor next to oil tank under stairs.

Pipe connects to sewer lateral.

Denison Ave

14 Denison Ave


Residential Building

2 ft. per square.

Hart Consults, LLC
05-001

Stonington SSES

15 Edgemont St
June 2022
Harbour Inn + Cottage



15 Edgemont Street
Bed + Breakfast Inn Building
Basement level


2ft per square

Hart Consults, LLC
05-001

Stonington SSES

18 Denison Ave
June 2022
Residential

Denison Avenue




2 ft per square.

18 Denison Avenue
Residential Building
Basement level

Hart Consults, LLC
05-001

Stonington SSES

20 Main St
June 2022
Apartments.




2 ft per square

20 Main Street
Residential Apartments.

Hart Consults, LLC
05-001

Stonington SSES
East Main Street

22 East Main St
May 2022
Commercial




22 East Main Street
Commercial Building

Hart Consults, LLC
05-001

Stonington SSES


27 Cottrell St.
May 2022
Apartments - Mystic River
Park



Hart Consults, LLC
05-001

Stonington SSES

32 Willow St.
May 2022
Residential



Willow Street

32 Willow Street
Residential Building

2 ft. per square


Hart Consults, LLC
05-001

Willow Street

Stonington SSES

35 Willow St

June 2022
Residential



2 ft per square


35 Willow St
Residential Building



Hart Consults, LLC
05-001

Stonington SES
Washington Street

36 Washington St.
June 2022
Residential



1ft per square


36 Washington Street
Residential Building

Hart Consults, LLC
06-001

Stonington SSES.

37 Willow St
June 2022
Residential


Willow Street.



37 Willow Street
Residential Building

Crawl space
confined space
no dimensions.

2 ft per square




Hart Consults, LLC
05-001

Stonington SSES

39 Denison Ave
June 2022
Residential Building

Denison Avenue



Basement level

39 Denison Avenue
Residential Building


N

2 ft. per square

Hart Consults, LLC
05-001

Stonington SSES

51 Church Street
May 2022
Residential



Apartments 6 to 9

Murphy Properties.
5 Residential Buildings.


51 Church Street
Residential
Crawl Space level.

4 ft per square

Hart Consults, LLC
05-001

Stonington SSES

51 Washington St.
June 2022
Residential




51 Washington Street
Residential Building

2 ft. per square

Hart Consults, LLC
05-001

Stonington SSES

56 Washington St.
May 2022
Residential



Washington Street


56 Washington Street
Residential
Basement level

2 ft per square

Hart+Consults, LLC
05-001

Stonington SSES

58 Washington St.
May 2022
Residential



Ground level
no subsurface level

58 Washington Street
Residential Building



2 ft. per square.

Building Inspection Forms

Owner:	
Address:	0 Edgemont.
Phone Number:	
Date / Time:	Wed. 06/29/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Mystic
Mirror +
Glass.

No illicit Connections

Slab on grade.

No sump.

Leads onto gr

Lateral not found.

2 9

Interior Sketch:




Edgemont

Owner:	
Address:	0 Edgemont.
Phone Number:	
Date / Time:	



Exterior Sketch:



Edgemont.

Owner:	Dennis & Terri
Address:	1 Sdon Ave.
Phone Number:	
Date / Time:	Friday, 6/3/22 11:30 AM



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

11:30


Crawl space.

No elect panel.
in basement.

No illicit connect.


Sump discharges
outside, see pic

Interior Sketch:



Owner:	
Address:	1 Solon Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Bob Peterson
Address:	1 Summit St.
Phone Number:	
Date / Time:	Wed. 7/6/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement

Sump, manual
to back yard.

Some leaders
into ground piped
out to back yard.

Interior Sketch:




Summit.

Owner:	
Address:	1 Summit St.
Phone Number:	
Date / Time:	



Exterior Sketch:

Summit St.



Leads
onto ground.

1.4 1.10 2.0

~~Leads~~
into
ground.

bulk
head

Leads
into ground.

Owner:	
Address:	1 Sylvia Ave.
Phone Number:	
Date / Time:	Wed. 6/1/22


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

*Sump Pump drains to yard.
Roof leads drain onto ground.*

*AC Drain.
dirt floor.*


Interior Sketch:



Owner:	
Address:	1 Sylvia Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:

Water



Owner:	Russ
Address:	2 Broadway Ave Ext.
Phone Number:	
Date / Time:	Thurs. 6/16/22.

Foundry
Machine.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on Grade.

No Sump.

Mystic River Foundry
Russell w/Holly
Machine.
Hydr. Repair.

Interior Sketch:

Can't locate lat


Leads onto gr.

No illicit connections

Owner:	
Address:	2 Broadway Ave Ext.
Phone Number:	
Date / Time:	



Exterior Sketch:



Broadway Ave Ext

Owner:	
Address:	2 Haley St.
Phone Number:	
Date / Time:	Thurs. 6/23/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement +
Sump discharge
onto st.


Haley St. Leads onto ground
No illicit connections

Interior Sketch:



Owner:	
Address:	2 Haley.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Robin Smith
Address:	2 Jackson Ave, Mystic
Phone Number:	(860) 912-0583
Date / Time:	Tues. 5/10/22 11 AM.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? **NO**
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer? **NO**
 - b. Storm/ground?
5. Floor Drains? **NO**
6. Internal Roof Drains? **Yes**
7. Electric / Breaker Box **✓**
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets **✓**

2-story
white
single family
cape w/ porch +
2nd story balcony
eaves
shingled roof.

4" CI lat
basement is in great
shape.

Interior Sketch:



Owner:	
Address:	2 Jackson Ave
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to ground.
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type) ✓
 - b. Driveways (type) ✓
 - c. Walkways (type) ✓
 - d. Trees (4" and larger – size and type) ✓
 - e. Shrubs / bushes ✓
 - f. Landscaped areas ✓
 - g. Decks / Patios ✓
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads No door access in rear to basement
 - j. Oil fill lines
 - k. Yard Drains No
4. Photos
 - a. Front of building ✓
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections ✓

Owner:	
Address:	2 Jackson Ave
Phone Number:	
Date / Time:	



Exterior Sketch:



2 roof leaders into ground
the rest drain into ground

Owner:	Jim Barton
Address:	2 Lincoln Ave.
Phone Number:	
Date / Time:	Thursday, May 19 11 AM



GIS Link # = 174-15-3

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Store Front Property
 'Holistic in Mystic'
 'Blinds + Designs'
 'Italian Deli'
 Apartment

Sump pump
connected to sewer

2 sumps
 - 1 day to day pump
 neighbors yard floods
 auto. op. goes to
 sewer

- 1 manual storm
 sump sends water
 to drive on Lincoln

Interior Sketch:



Owner:	
Address:	2 Lincoln Ave
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	2 Lincoln Ave
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	2 Main St. OM
Phone Number:	
Date / Time:	Sat. 7/2/22



potential

No interior insp.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Leads onto ground
No cleanout or vent found
No sump pump discharge found.

Interior Sketch:

Owner:	
Address:	2 Main St OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	#2 Roosevelt Ave
Phone Number:	
Date / Time:	Tues. 5/31/22

6/1/22

Mystic Amtrak



potential illicit connect.

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump? *yes.*
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? *No*
6. Internal Roof Drains?
7. Electric / Breaker Box *not visible*
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Need to speak w/ someone
Not completed

Did not locate sum of
Sump tank basement
between 11 & 20m

Access to crawl space on
door in interior of building

Interior Sketch:



Owner:	
Address:	2 Roseville Ave - front
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	2 Room 4 - Amherst
Phone Number:	
Date / Time:	



open 8AM - 2PM.

Exterior Sketch:



Owner:	
Address:	2 Stafford St.
Phone Number:	
Date / Time:	Wed. 6/8/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on grade.

No sump.


Leads on to ground.

Interior Sketch:

picture in rear, could be waste water.

Owner:	
Address:	2 Stafford.
Phone Number:	
Date / Time:	

Exterior Sketch:



Sketch.




Owner:	Berkshire Hathaway
Address:	2 Williams Ave
Phone Number:	
Date / Time:	Tue, 5/31/22 ~ 2:40

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



Owner:	
Address:	2 Williams
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	2 Williams Ave
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Harry Boardson, Noank Shipyard.
Address:	4 Washington
Phone Number:	
Date / Time:	Wed. 6/22/22.



Interior Inspection:

~~Red 36~~

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Noank Shipyard.
Harry Boardson

emailed. info@noankshipyard.com
6/14/22.

Interior Sketch:

Wash: ↑ N

55 Willow } Plastic Surgery office.
Not owned by Noank.



No gutters
No basement.

Willow


#4

→ sump pump discharges outside.

Owner:	
Address:	# 2 + 4 Washington
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Harry Bondesen
Address:	Red 36 Restaurant
Phone Number:	also owned by Noank Shipyard.
Date / Time:	Wed. 6/22/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) - beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

has holding tank
on stilts.

No illicit connections

No crawl space -

No sump.

Interior Sketch:

Noank Shipyard.

- Red 36 Restaurant : 2 Washington
- Shipyard Warehouses : 2 Washington.
- Residence : 4 Washington.

Stilts no basement or crawl space. Gutters to retention area. tube to bioretention area.

on grade. No sump No gutters

Sump to outside holding tank then into a sewer. Going to be rerouted. best located.

Current waste sent to a

Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:

My Map

No legend

John Johnson for Allen Spool Mill
Thomas River Properties.

#2 Washington
Noak Shipyard

#4 residence

1 parcel

Red 36

Mill
other owner

Warehouse
slab

Warehouse

Red 1
on grade

#4 Washing
lower

doctors
office

200ft

Esri Community Maps Contributors, Town of Groton, MassGIS, UConn/CTDEEP, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA

Owner:	
Address:	3 Broad Way.
Phone Number:	
Date / Time:	Tues. 6/7/22 1:30.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Not Illlicit.

Leaders discharge
on to ground.

Solar panels on roof plumbed to
pool, used for heating.

Interior Sketch:




Broadway

Owner:	
Address:	3 Broadway.
Phone Number:	
Date / Time:	



Exterior Sketch:

Broadway.



Owner:	
Address:	3 Jackson Ave.
Phone Number:	
Date / Time:	Wed. 6/22/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Vacant house

No response

Notice still on door.

Windows to basement visible.


Lateral located.

Interior Sketch:

Owner:	
Address:	3 Jackson Ave.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Pam Zalinsky
Address:	3 Main St. OM
Phone Number:	(860) 501-2031
Date / Time:	Tues. 7/12/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
No Sump pump
Leads onto
ground.
N
←


Main St.

Interior Sketch:



Owner:	
Address:	3 Main St OM.
Phone Number:	
Date / Time:	

Exterior Sketch:



Shell Station - Henny Penny

Owner:	
Address:	2 Roosevelt Ave, maybe 3 Roosevelt
Phone Number:	
Date / Time:	Wed. 6/22/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

GIS Map lists as
48 Broadway Ave and
3 Roosevelt.


Slab on grade.
Could not locate clean out.
Leadens onto ground.

Interior Sketch:

No illicit connections.

Owner:	
Address:	Henny Penny - Shell Station
Phone Number:	2 or 3 Roosevelt Ave.
Date / Time:	

Exterior Sketch:



Sketch.

5

Owner:	Howard Turner
Address:	3 Summit St.
Phone Number:	(800) 912-0813
Date / Time:	Wednesday, May 18 5PM



GISLink # = 174-11-10


Interior Inspection:

most likely not

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Looks like 4" ID
6" from ceiling
2' off ft
4' crawl space
No sump pump
crawl space

Interior Sketch:



Summit St

Owner:	
Address:	3 Summit St
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	3 Summit St
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	3 Sylvia.
Phone Number:	
Date / Time:	Wed. 6/8/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit
connections
gravel.
basement
no sump.


leaves
discharge on to
ground.

Interior Sketch:



Owner:	
Address:	3 Sylva.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Ari.
Address:	4 Broadway Ave Ext.
Phone Number:	
Date / Time:	Thursday 6/16/22



Interior Inspection:

3:30 - 4 PM
today

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) - beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Professional Building

Simonds & Company Kitchens by Design.

FamilyWise - Behavior Solutions.

Maxim Skin Med Spa.

Le Spa

Assisi Institute.

→ Just recently purchased by new person.

[Ari Bigi
(347) 225 - 6599.
called & scheduled.

Interior Sketch:

No basement.
Slab on grade.
on stilts const.

No gutters

No known Drains.


No illicit connections.

Owner:	
Address:	A Broadway Ave Ext.
Phone Number:	
Date / Time:	

Exterior Sketch:

building on
pillars

No exterior leadus.



Broadway Ave Ext.

Owner:	
Address:	4 Haley St.
Phone Number:	
Date / Time:	Wed. 6/15/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections
Basement,
access from inside.

No sump.

Interior Sketch:




Owner:	
Address:	4 Halsey.
Phone Number:	
Date / Time:	



Exterior Sketch:

Halsey St



Owner:	Irene
Address:	4 Jerome Ave.
Phone Number:	
Date / Time:	Tues 6/7/22 9:45Am




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Sump.
No illicit connect.
Basement.


Interior Sketch:



Jerome.

Owner:	
Address:	4 Jerome.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	4 Main St - CM.
Phone Number:	
Date / Time:	Sat - 7/2/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

House is being renovated
and is empty.

Leads are disconnected
but there no in ground
pipes.


Lat. vent found.
no clean out.

Interior Sketch:

Appears to have basement.

Owner:	
Address:	4 Main St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Bob- Mercer.
Address:	4 Mill Street.
Phone Number:	
Date / Time:	Fri. 6/3/22 ~ 1:30



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections


No Sump pump.
Roof drains
on to gr.

No external. cleanout.
for sewer.

finished basement.

\$


Interior Sketch:



Owner:	
Address:	4 Mill St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Sketch.

Owner:	
Address:	Noble Smokehouse - 4 Roosevelt.
Phone Number:	
Date / Time:	Tues. 5/31/22 6/3/22



sump only
not leaders

Needs to be inspected no later
opens Wednesday @ 12pm

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump is connected
to sewer.

Leads are not connected.

Interior Sketch:

Roosevelt.


under house
portion

lat.

dirt crawl space
significant odor (previous
sewer backups)
→ determined it to be a
potential health risk
so no measurements
were taken.

Owner:	
Address:	4 Rosemead - North Hollywood
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	4 Smith St
Phone Number:	
Date / Time:	Sat. 7/2/22

potential
owner plans on
changing 1 leader.

HART CONSULTS
EXPERTISE IN WATER AND WASTE WATER SOLUTIONS LLC

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Basement

Weekend visit 7/2/22

Sump discharges
to street.
Leads onto ground
1 into ground.

Smith.

Interior Sketch:



Owner:	
Address:	5 Edgewood mont.
Phone Number:	
Date / Time:	Wed., June 1, 2022 ~ 1:40 PM.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Sump.

Lat. in Garage.

[Also owns 16 Broadway Ave Exh.]

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	5 Edgemont
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Jim Santos
Address:	5 Haley St.
Phone Number:	
Date / Time:	Mon. 6/27/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Crawl Space.
Leads onto ground.
Lat located
cleanout.

No illicit connections
no sump.


Interior Sketch:



Haley St.

Owner:	
Address:	5 Halcy St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Halcy St.

Owner:	
Address:	5 Jackson Ave.
Phone Number:	
Date / Time:	Tues 10/14/22



Sump pump discharged outside
Roof leaders onto ground.
Leader located.

No illicit connections.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Jackson.




Interior Sketch:



Owner:	
Address:	5 Jackson Ave.
Phone Number:	
Date / Time:	



Exterior Sketch:



Jackson

Owner:	Wayne.
Address:	5 Lincoln.
Phone Number:	
Date / Time:	Ned. 6/29/22.



No illicit connections

Basement.

Leader onto ground

Sump to yard.

could not find discharge
but thru opposite
wall from lat.


Lat located, cleanout underground
not visible.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Lincoln.

Interior Sketch:




Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:

Lincoln



Owner:	Mr. Cummins
Address:	5 Stanton.
Phone Number:	
Date / Time:	Tues. 6/14/22

Potential - No sketch.



Potential Leach connected.
Not sump pump.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) - beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Resident disconnected from
sewer @ a cost of \$800
last year - discharges
to lawn.

1 leader goes
into ground,
looks clogged.

Interior Sketch:




Owner:	
Address:	5 Stanton Pl.
Phone Number:	
Date / Time:	



Stanton.

Exterior Sketch:



Owner:	Dayleen
Address:	5 Summit St.
Phone Number:	(800) 536-9379.
Date / Time:	Tues. 6/21/22.

Sketch.

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Church.

2 Sumps tied in to sewer.

"Dong has been here and agreed w/ resident that there aren't options for discharge."

Interior Sketch:




Summit

*Leads onto ground
No additional drains.*

Owner:	
Address:	5 Summit.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	5 Sylvia
Phone Number:	
Date / Time:	


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump discharge to
lawn.
No leadins.

No illicit connections

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	5 Sylvia Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Diana Pagonis
Address:	6 Haley Street
Phone Number:	(617) 458-9013
Date / Time:	Tuesday, May 31 st , 2022



G15 Link # 182-3-5

1 PM

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No sump pump

CI pipe mit 2 Lateral vent
pyramida vent ex. ventricul
h. l. vent.

most likely gas to push out
not supplying in base

Henry S.

Interior Sketch:



Willen,

Owner:	
Address:	60 Halcyon St.
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	Mr. Bourgeois
Address:	6 Haley's Way
Phone Number:	
Date / Time:	Thurs. 6/9/22 3:30 PM




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections

Crawl Space. concrete floor shallow
No Sump pump. couldn't crawl in to lat.
Leads ✓


Interior Sketch:



Owner:	
Address:	66 Haley's Way.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Ron Ruggiero (+ Ann)
Address:	6 Jackson Ave
Phone Number:	(603) 321-9494
Date / Time:	Tues. May 17, 2022 1 PM



GIS Link # = 182-5-16

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? No
6. Internal Roof Drains?
7. Electric / Breaker Box ~~See~~ NA
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets NA

Crawl space.

46" from ceiling
20" from gr.

Interior Sketch:

~ 5' height crawl space
dirt floor



Owner:	
Address:	6 Jackson Ave.
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	Russ
Address:	6 Lincoln Ave.
Phone Number:	
Date / Time:	Thurs. 6/16/22



Also owns Foundry / Machine.

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump to St.
Leads onto ground.

No illicit connections


Lincoln.

Interior Sketch:



Owner:	
Address:	66 Lincoln Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	6 Mill St.
Phone Number:	
Date / Time:	Fri. 6/3/22 ~ 2pm.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

May be septic.

No illicit connections


Leads on to ground.

No sump



She said the basement is completely dry and hasn't had any moisture in it since they bought it in 1977.

Interior Sketch:




1/5/20

Owner:	
Address:	6 Mill
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Ann Barnhart
Address:	7 Edgement St, Mystic
Phone Number:	(800) 514-2241
Date / Time:	Saturday, April 30, 2022 2PM




Saxmundum
near Ipswich


Interior Inspection:

- Slab on grade construction, no basement
1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
 2. Additional sanitary connections? 2 buildings, 1 lateral and cleanout per building
 3. Clean/clear water connections? see photos + sketch
 4. Sump Pump? No
 - a. Sewer? NA
 - b. Storm/ground? NA
 5. Floor Drains? NA
 6. Internal Roof Drains? NA
 7. Electric / Breaker Box No basement
 - a. Location
 - b. Amp capacity (if visible)
 8. Outlets No basement

Interior Sketch:



Going to jack up house




2/

Owner:	
Address:	7 Edgemont St, Mystic
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains *NA*
- b. Patio Drains *NA*
- c. Driveway Drains *NA*
- d. Lawn Drains *NA*
- e. Foundation Drains *NA*

2. Roof Leader Discharge

- a. Location *to ground see sketch*
- b. Discharge to *ground*

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type) *NA*
- b. Driveways (type) *pass to front door*
- c. Walkways (type) *to front door*
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes *NA*
- f. Landscaped areas *Lawn*
- g. Decks / Patios *parking in front*
- h. Irrigation valves or sprinkler system
- i. Bulkheads *NA*
- j. Oil fill lines *NA elect*
- k. Yard Drains *NA*

4. Photos

- a. Front of building ✓
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections ✓

Owner:	Acme Wiring - Mike DeBella
Address:	7 Broadway Ext, Mystic
Phone Number:	(800) 572-0511
Date / Time:	Tues, 5/10/22 9AM.

GIS Link = 174-22-1

#2



~~Planet~~ Planeta → correct sp.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? NA
3. Clean/clear water connections?
4. Sump Pump? 2
 - a. Sewer? – yes
 - b. Storm/ground?
5. Floor Drains? Capped / Filled.
6. Internal Roof Drains?
7. Electric / Breaker Box — 9 total throughout facility
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Manufacturing Facility

1 building

Multiple Buildings
Administration building
Production Warehouse.

Drain to river
from 100 ft

2 sump pumps

1 to sewer


1 unknown

Floor drains Filled.

slab on grade

Roof drains

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

not visible.
ground

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains No

4. Photos

- a. Front of building ✓
- b. Confirmed or suspected illicit connections ✓
- c. Cleanout – if no illicit connections ✓

✓ sump pump in loading dock

Gravel along walkways
and drives for drain
Roof is flat, collected and
sent East to back
of building.

Reinforced walls +
elevated access around
building for water

Owner:	John.
Address:	7 Jackson Ave.
Phone Number:	
Date / Time:	Thurs. 6/16/22.



Interior Inspection: Residence.

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Basement - crawl space
No Sump Pump.


Leads on to gr.

No illicit connections

Jackson Ave.




Interior Sketch:



Owner:	
Address:	7 Jackson Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	7 Lincoln Roosevelt.
Phone Number:	
Date / Time:	Fri. 6/24/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Store fronts

Slab on Grade.

Mystic River Hairs Nails
no sump.

Eldred's Auctioneers

The Ditty Bag.

Interior Sketch:

Cleanout located.

Leads onto gr.

No known sump pumps.

Owner:	
Address:	7 Smith St.
Phone Number:	
Date / Time:	Saturday 7/2.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

land lord.
Mitch.
Bovarnick.
owner for basement
access.


Leads into ground.
Lat cleanout located.

Interior Sketch:

Tenant went in to get cell phone
for land lord #
Never came back.

Owner:	
Address:	7 Smith St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	7 Sylvia.
Phone Number:	
Date / Time:	Wed. 6/8/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump pump discharges outside. – see pic.

No gutters/leadus

No illicit connections.

Interior Sketch:




Owner:	
Address:	7 Sylvia.
Phone Number:	
Date / Time:	



Exterior Sketch:

Sylvia -

No gutters.



Owner:	Lilli Rebrich
Address:	8 Jackson Ave.
Phone Number:	
Date / Time:	Thurs. 6/8/22 11AM.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connect.

No sump -
Crawl Space - shallow -
concrete floor.
N

Interior Sketch:

Roof leaders discharge into
ground, flow sent through
a pipe out of yard - see pic.




sewer lat.
down to base of
foundation

Jackson.

Owner:	
Address:	8 Jackson Ave.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Debbie Barry
Address:	8 Main.
Phone Number:	
Date / Time:	Thurs. 6/9



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No sump.

No gutters.

Crawl space


Interior Sketch:



Owner:	
Address:	8 Main St.
Phone Number:	
Date / Time:	



Exterior Sketch:



No gutters.

Owner:	
Address:	#8 Mill.
Phone Number:	
Date / Time:	Fri. 6/3/22 ~ 2 PM.



Interior Inspection:

Bob Mercer, gave me access to this house.
James Coker.

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Readers discharge to ground.


No Sump.

~~Basement is dirt.~~

~~she said.~~


Lat. may go to septic system?

Interior Sketch:



Owner:	
Address:	8 Mill St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	6 Mill St.
Phone Number:	
Date / Time:	Fri. 6/3/22 ~ 2pm.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

May be septic.

No illicit connections


Leads on to ground.

No sump



She said the basement is completely dry and hasn't had any moisture in it since they bought it in 1977.

Interior Sketch:



Handwritten signature/initials

Owner:	
Address:	8 Reynolds Hill
Phone Number:	
Date / Time:	Wed. 6/29/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.


Lateral - internal
locat.
not exten

Leads onto gr.

No illicit
connections

Interior Sketch:


Reynolds Hill



Owner:	
Address:	8 Reynolds Hill.
Phone Number:	
Date / Time:	



Exterior Sketch:



Reynolds Hill.

Owner:	Patrick Hayes Kathy
Address:	8 Stafford St, Mystic
Phone Number:	(800) 642-3990
Date / Time:	Wed 5/11/22. 10 AM



GIS Link.# = 174-23-4

Residence


crawl space.

Interior Inspection:

1. Lateral location:
 - a. Horizontal *in crawl space, see photo*
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? *No*
3. Clean/clear water connections? *sump pump discharge*
4. Sump Pump? *to road, see photo*
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? *No*
6. Internal Roof Drains? *No*
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No lead-ins on garage

Interior Sketch:



Owner:	
Address:	8 Stafford
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

No

2. Roof Leader Discharge

- a. Location
- b. Discharge to

see sketch

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

sketch

No

No


4. Photos

- a. Front of building ✓
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections ✓

Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Pat Wheeler
Address:	9 Haley Street
Phone Number:	(800) 908-1068
Date / Time:	Tuesday, May 17, 2022



GIS Link # → 182-4-7

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

[portable trash pump, not hooked up]
Rarely get water in basement

was CI

25" from ff
lateral.
50" from ceiling

Interior Sketch:



Owner:	
Address:	9 Haley St
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	9 Haley St
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Candace Elizabeth
Address:	10 Alden Street
Phone Number:	(800) 608-3403
Date / Time:	Tues., May 17, 2022 5PM



GIS Link # =

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Plans to divert sump to road drain

6' Crawl space floor gravel

Sump plumbed to sewer

please note that sewer lateral DOES go out of the back of the house

Interior Sketch:



Owner:	
Address:	10 Alden St.
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	10 Alden
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	10 Jackson Ave.
Phone Number:	
Date / Time:	Tues. 6/14/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump discharges outside
Leads on to ground

No illicit connections.


Interior Sketch:



Jackson.

Owner:	
Address:	10 Jackson.
Phone Number:	
Date / Time:	

Exterior Sketch:



Jackson Ave.

Owner:	Debbie Berry
Address:	10 Main St.
Phone Number:	
Date / Time:	Thurs. 6/9/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No sump

Slab on Grade.

~~No bus~~

No illicit connect


Interior Sketch:

Owner:	
Address:	10 Main St.
Phone Number:	
Date / Time:	



Exterior Sketch:

Main St.



Owner:	
Address:	10 Reynolds
Phone Number:	
Date / Time:	Thursday 6/9/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit Connections

No sump.
Leads on to ground.

Summit.


Interior Sketch:



Owner:	
Address:	to Reynolds Hill
Phone Number:	
Date / Time:	



Exterior Sketch:



Sketch.

Owner:	Mystic River Park - Dick Sylvestre.
Address:	10 Cottrell St.
Phone Number:	(800) 572-7244
Date / Time:	Tuesday, May 31 st 2022. 9 AM



Not sure of GIS Link.
Mystic Fire District? ✓ yes.

6 # of Buildings.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

GIS# 182-1-13
(#10, 12, 27, 28, 29)

GIS# 182-3-2
(#25)

All roof leaders go
to ground.

10

12

25

27

28

29

12 - Slat on ground
No sump
storm let. to ground

10 crawl space
no sump
storm let ✓
leaders to ground

28 crawl space
disconnected


25 - basement
sew. ext. pipe to line running to
- leading to ground
leaders to ground

Interior Sketch:

(see p. 2)



lat
16" CI



Input sheet

Owner:	
Address:	#10, 12, 25, 27, 28, 29 Hill
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- Window Drains
- Patio Drains
- Driveway Drains
- Lawn Drains
- Foundation Drains

2. Roof Leader Discharge

- Location
- Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house


- Fence (height & type)
- Driveways (type)
- Walkways (type)
- Trees (4" and larger – size and type)
- Shrubs / bushes
- Landscaped areas
- Decks / Patios
- Irrigation valves or sprinkler system
- Bulkheads
- Oil fill lines
- Yard Drains

4. Photos

- Front of building
- Confirmed or suspected illicit connections
- Cleanout – if no illicit connections

*#29 main space
don't have a*



#27 basement



Owner:	
Address:	10, 12, 25, 27, 28, 29 Potomac
Phone Number:	
Date / Time:	



Exterior Sketch:



5/31/22



Owner:	Claude. Harbour Inn + Cottage.
Address:	11 Edgemont St.
Phone Number:	(800) 572-9253
Date / Time:	Wed. June 1, 2022 ~ 11 AM.



Interior Inspection:

The Cottage.

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Not able to access #11
because someone is
staying there and owner
is elderly.

Interior Sketch:

Sewer from Cottage @ 11 is connected
to sewer in # 15 Edgemont.

Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections


Harbor Inn & Cottage.

Owner:	
Address:	<i>11 Edgemont St</i>
Phone Number:	
Date / Time:	<i>6/1/22 ~ 11 AM.</i>



Exterior Sketch:

"Cottage"



Owner:	
Address:	11 Jerome.
Phone Number:	
Date / Time:	Wed. 6/1/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connect.
Sump - discharges
to lawn.

Interior Sketch:



Owner:	
Address:	11 Jerome.
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	11 Jerome.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Mill Building - Old Mystic
Address:	11 Mill or 11 Whitehall
Phone Number:	
Date / Time:	Tues. 6/7/22. ~ 11:30 AM.

M.I.
11 Main St.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections

Eye Glass Loss.

Hair Salon
Barber Shop
Aesthetician
JEM Builders.
4th Henry Productions
Wild Love Hair Studio.

No basement.

Can't locate sewer lateral.
or clean out.


Interior Sketch:

Raytheon.

Storm drains on
street.

Owner:	
Address:	11 Main St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	James Santos
Address:	12 Broadway Ave Ext.
Phone Number:	
Date / Time:	Tues. 6/21/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.

Lat located.


Leads onto ground

Sumps onto ground.

No illicit connections

Interior Sketch:

Allowed me to
access basement
w/o being present




Broad.
Ave
Ext

Owner:	
Address:	12 Broadway Ave Ext.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Paul.
Address:	12 Jackson
Phone Number:	
Date / Time:	Wed. 6/15/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections.

Sump discharge to yard.


Lat located.

No gutters.

2 basements


- new addition
- old section (this is where the lat + sump are.)

Interior Sketch:



Owner:	
Address:	12 Jackson.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	12 Jerome
Phone Number:	
Date / Time:	Wed., 6/1/22 ~ 3:30




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Sump.
 No illicit connections
 No roof leaders.
~~base~~ crawl space.

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	12 Jerome.
Phone Number:	
Date / Time:	Wed. 6/1/22 ~ 3:30

Exterior Sketch:



Owner:	Mystic Packer Building
Address:	12 Roosevelt Ave
Phone Number:	(800) 536-4855
Date / Time:	Wed 5/11/22 2pm

Sketch

#5



John Holstein
Glen - Maintenance
Contractor should
be allowed.

G/S # = 174-17-3


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump pump
connected to sewer

1 known lateral.
Water St. side

Could not access full crawl
space because of standing
water.



Owner:	
Address:	12 Solon
Phone Number:	
Date / Time:	Sat. 8/2/22



potential.
No interior insp.

Rental property

basement windows visible

PVC pipe from rear of house thru foundation entering ground.

gravel patch may be for pipe.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

Owner:	
Address:	12 Solon
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Daniel Moak
Address:	13 North Stonington Rd.
Phone Number:	
Date / Time:	Thurs 6/9/22 4 PM.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


*Sump Pumps discharged to stream
See pics.
Roof Leaders discharge onto ground
No illicit connections
Basement.*

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	13 Smith St.
Phone Number:	
Date / Time:	Wed. 6/8/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Previous house was demolished.

New building being constructed.

Crawl space, access from 1st floor.

Interior Sketch:

No sump pump @ this time.


Pic of cleanout.

New Under Construction

Owner:	
Address:	13 Smith St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Smith.

Owner:	Marilyn Citron
Address:	14 Denison
Phone Number:	
Date / Time:	Tues. 6/28/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Most likely sump tied into sewer, not fully visible.

Some leaders go into ground to dry well or driveway pipe.

Garden House
Slab on grade

Main House
basement.

Interior Sketch:




Denison.

Owner:	
Address:	14 Denrson.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	14 Edgemont.
Phone Number:	
Date / Time:	Wed. 6/29/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Crawl Space.


No gutters

No sump.

No illicit connect

No sump

Interior Sketch:





Edgemont.

Owner:	
Address:	14 Edgemont.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	14 Jackson.
Phone Number:	
Date / Time:	Wed. 6/15/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
Sump pump sends flow
to back yard.

Lateral located.

No illicit connections.

Interior Sketch:




Owner:	
Address:	14 Jackson.
Phone Number:	
Date / Time:	



Washington

Exterior Sketch:

No gutters



Harbour Inn & Cottage.

Owner:	Claude.
Address:	15+11 Edgemont.
Phone Number:	(866) 572-9253
Date / Time:	Wednesday, June 1 10:30 AM.

Sketch.



Interior Inspection:

Separate.

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

2 buildings.
- Main Inn
- Cottage.


Cottage sewer penetrates the Inn @ basement & ties into the sewer system.

Roof Leaders discharge onto the ground.

Does not appear to be any drive or lawn drains.

Owner is elderly.

Interior Sketch:



Owner:	
Address:	15 Edgemont
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	Harbour Inn + Cottage
Address:	15 Edgemont St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	15 Washington
Phone Number:	
Date / Time:	Tues. 6/14.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No illicit connections

No leadus
Leadus removed but where the
down spouts are do not have ground
penetration

Sump into yard.


Washington

Interior Sketch:



Owner:	
Address:	15 Washington St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	16 Broadway Ave Ext.
Phone Number:	
Date / Time:	Wed. June 1, 2022 ~ 1:40 PM.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Bulk head.

Sump pump.


Lat ✓.

No illicit connect.

Crawl Space.

Owned by 5 Edgemont.

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	16 Broadway Ave Ext.
Phone Number:	
Date / Time:	

Exterior Sketch:

Broadway Ave Ext.



Owner:	
Address:	16 Main St - OM
Phone Number:	
Date / Time:	Tues. 6/7/22 2PM.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Set-back off street.

No basement
Crawl space
inaccessible.

Cleanout located.

No illicit connect.


No sump pumps.

Interior Sketch:

Owner:	
Address:	16 Main St. OM
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	160 Solon.
Phone Number:	
Date / Time:	Saturday 7/2/22

potential.
No interior inspection.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Rental property.
Lat not located.


Irrigation system

No visible pipes other
than leaders

Interior Sketch:

Owner:	
Address:	16 Solon.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	17 Solon Ave.
Phone Number:	
Date / Time:	Fri. 6/3/22 ~9AM.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Door knock.


No illicit connections

Roof leads into ground
~~through~~ for discharge
into yard.

Resident said she never
received a notice.


Bulk head in back.
floor is grushed stone.

Interior Sketch:



Owner:	
Address:	17 Solon Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Rob + Andrea
Address:	18 Denison
Phone Number:	
Date / Time:	Mon. 6/27/22. 2:30



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump connected to sewer.
Leads onto gr.



Denison.



Interior Sketch:



Owner:	
Address:	18 Denison
Phone Number:	
Date / Time:	



Exterior Sketch:



Denison Ave.

Owner:	
Address:	18 Main St OM.
Phone Number:	
Date / Time:	Sat. 7/2/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sewer lat cleanout located.
Leads onto ground.

No visible sump pump discharge.


Interior Sketch:

Owner:	
Address:	18 Main St. OM.
Phone Number:	
Date / Time:	



Exterior Sketch:

Main St.



Owner:	
Address:	18 Stafford St.
Phone Number:	
Date / Time:	Tues. 5/31/22



not on list but highlighted. - GIS # ?

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) - beneath finished floor
2. Additional sanitary connections? No
3. Clean/clear water connections?
4. Sump Pump? No.
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box split
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets NA

Slab on gr.

No sump pump

2 build.
→ see next page

3 buildings
2 @ this location

18A on Separate sheet.

Interior Sketch:

Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections


Owner:	
Address:	18 Stafford
Phone Number:	
Date / Time:	

Mystic Marina



Mystic Cove

Exterior Sketch:



Owner:	
Address:	19 + 21 Jackson.
Phone Number:	
Date / Time:	Wed. 6/15.



Peter.

Mr. Zelken.

owner. not here.

Staff allowed me access.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on grade.

No sump.

Roof leaders discharge
on ground.

Could not locate lateral.

Interior Sketch:


Mystic Oil Company, Inc.

Castle Hill Audio Video.

No illicit connections.

Owner:	
Address:	19-21 Jackson.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Phil
Address:	20 Denison.
Phone Number:	
Date / Time:	Sat. 7/2/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.
 Lat loc. int. - not found ext.
 No sump.
 No illicit connect. ✓

Denison



Interior Sketch:



Owner:	
Address:	20 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Whaler's Inn
Address:	20 East Main St., Mystic
Phone Number:	(603) 944-2904
Date / Time:	Wed. 5/11/22



GIS Link # =

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Multiple Addresses

#4

#9 Cottrell

#20 East Main

#

7 build
5 on main
1 on 2 other.

Head of Engineering

3 sump pumps

Goes into their own system
Underground Stormwater
discharge system


Chambers

have a permit to discharge
to storm

Closed loop system
water ~~is~~ distributed into
ground discharge under
2 parking lots

Interior Sketch:

Roofing drain → into system



Roof leaders

- some buildings are into
system, some onto ground.

"System"
Stormtech-tech
SC 740"

Owner:	
Address:	
Phone Number:	
Date / Time:	



Scum on slab-


External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:



N



1865 House

Stonington House

semp.



East Main Street

Library

Main Inn

SWD

Noank House

semp all others

THE WHALER'S INN

11' Sis

fed into system

semp

Ice 2nd Floor

Lobby

Hoxie House

electric

slab on gr.

latinal comes out



Fire Lane



11 Cottrell slab on gr.

Cottrell Street

latinal.

4 E. MAIN ST

slab on gr.

Owner:	
Address:	20 Jackson Ave.
Phone Number:	
Date / Time:	Wed. 6/15/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Leaders onto ground,
Sump Pump goes to yard!

Basement

No illicit Connections


Interior Sketch:

Jackson



Owner:	
Address:	20 Jackson Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Sketch:

Owner:	
Address:	20 Main St.
Phone Number:	
Date / Time:	Tues, 6/7/22 2:15pm.



Matt

O'Grady

(800) (908) 8030

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

set back off of street.

Main St

Rental property-

Interior Sketch:



Sump connected to sewer.


Leads into ground

Owner:	
Address:	20 Main St
Phone Number:	
Date / Time:	



Exterior Sketch:

Set-back.





**HART
CONSULTS**
EXPERTISE IN WATER AND WASTEWATER SOLUTIONS

1. Lateral location:

- 10' NE corner.

4" d CI
5' below ceiling
Sump
pipe to driveway

base ment
water in spring

basement
~~concrete~~ stone + mortar
unfinished floor.

No yard or driveway
drains.
drywell in backyard.

Roof leads to
street through piping

[illegible]

Owner:	
Address:	20 Mistucket
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains No
- b. Patio Drains No
- c. Driveway Drains No
- d. Lawn Drains No
- e. Foundation Drains No

2. Roof Leader Discharge

- a. Location see sketch
- b. Discharge to ground.

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type) NA
- b. Driveways (type) paved.
- c. Walkways (type) No
- d. Trees (4" and larger – size and type) No
- e. Shrubs / bushes
- f. Landscaped areas No.
- g. Decks / Patios No
- h. Irrigation valves or sprinkler system No
- i. Bulkheads yes - see sketch.
- j. Oil fill lines
- k. Yard Drains No

4. Photos

- a. Front of building ✓
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections ✓

Owner:	
Address:	20 Misturt
Phone Number:	
Date / Time:	



Exterior Sketch:

See Page 1

Owner:	Dan Terrell
Address:	21 Denison.
Phone Number:	
Date / Time:	Mon. 6/27/22 2pm

potential.
leader.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Basement.

No sump.
Lat. located inside.
no cleanout outside.

Leads varies.
1 goes into ground
rest onto ground.

Denison

Interior Sketch:




Owner:	
Address:	21 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Washington St.



Owner:	
Address:	Old Mystic Fire - 21 N. Stonington
Phone Number:	
Date / Time:	Thurs. 6/16/22.

potential - no sketch



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) - beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Leads into drain/storm
see pics.


No confirmed illicit connections

Slab on grade.

No sumps.

Clean out located.

Interior Sketch:




Owner:	
Address:	21 N. Stonington Rd.
Phone Number:	
Date / Time:	



N. Stonington.

Exterior Sketch:



Owner:	
Address:	21 Stafford
Phone Number:	
Date / Time:	Sat. 7/2/22

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Basement.

No gutters.

No illicit connections. No external cleanout.


Sump to backyard.

Interior Sketch:



Owner:	
Address:	21 Stafford.
Phone Number:	
Date / Time:	

Exterior Sketch:



Stafford



Down wire

Owner:	Bill Coyle
Address:	22 East Main, Mystic
Phone Number:	(800) 460-6998
Date / Time:	Wed. 5/11/22



3 elect panels GIS Link = 182-4-10

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? No.
6. Internal Roof Drains? NO
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

see sketch

3 elect panels

Roof Leaders to sidewalk.

Bulk head.

4" CI
5' from ceiling
19" from floor

E Main.

1st

58"

50' x 20'
int. dims

1 outlet

oil tank



sump

disconnect

outlet 1

Interior Sketch:

see sketch
up stairs
NA

Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building ✓
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	22 Jackson Ave.
Phone Number:	
Date / Time:	Wed. 6/15/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump discharges to yard.


Leads to gr.

Basement

Lat loc.

No illicit connect.

Interior Sketch:




no spno prodid
2# drains

Jackson

Owner:	
Address:	
Phone Number:	22 Jackson
Date / Time:	

Exterior Sketch:



Owner:	Citizens Bank.
Address:	23 Broadway Ave.
Phone Number:	
Date / Time:	Wed. 6/22/22.

potential. leads.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on Grade.
No known
drains.


Some leads
go into the
ground.

Interior Sketch:

Owner:	
Address:	23 Broadway Ave.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	23 Denison Ave.
Phone Number:	
Date / Time:	Tues. 6/21/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No illicit connect.
 Ident. lat lec.
 Leaders onto gr.
 Sump pump on to gr.

Interior Sketch:



Owner:	
Address:	23 Denison.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	23 Jackson Ave -
Phone Number:	
Date / Time:	Wed. 6/29/22



Wed.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on Grade.

No Sump.

No illicit connect. Leaders onto ground

Lat not located.


Interior Sketch:

Mystic Stainless AISI 3

Owner:	
Address:	23 Jackson.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	24 Broadway Ave Ext.
Phone Number:	
Date / Time:	Wed., 6/1/22 ~ 2PM.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

2 sump pumps
 piped into back yard.
 → old piping is visible.
 that went to sewer.
 but it's disconnected.

Interior Sketch:



Broadway. Ave. Ext.



Owner:	
Address:	24 Broadway Ave Ext
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	24 Broadway Ave Ext
Phone Number:	
Date / Time:	



Exterior Sketch:



Broadway Ave Ext.



Owner:	Grass + Bone
Address:	24 East Main St.
Phone Number:	
Date / Time:	Mon. 6/27/22.

potential.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Business closed.
Up for rent.

No internal inspection

Slab on grade.

Could not locate lat.

Leads onto ground.

No visible sump pump discharge.

Interior Sketch:

Owner:	Ren Dutton
Address:	24 Jackson Ave.
Phone Number:	(
Date / Time:	Wed. 6/22/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Drainage on Jackson
prev. storm drain
from


Basement

No illicit connections
2 Sumps

Jackson

leads into gr.


Interior Sketch:



Owner:	
Address:	24 Jackson
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Loise Carr
Address:	24 Lincoln Ave.
Phone Number:	
Date / Time:	Fri. 6/24/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump pump
discharges outside.
Leads onto ground.


Lat. located.
+ vent. N

No illicit connections

Lincoln

Basement

Interior Sketch:




Owner:	
Address:	24 Lincoln
Phone Number:	
Date / Time:	



Exterior Sketch:

~~Circle~~ Lincoln.



Owner:	
Address:	24 Main St. OM.
Phone Number:	
Date / Time:	Tues. 6/28/22.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

*No Sump
Basement
Lat located
ext. Vent located.
Leads into ground*

No ill/rct connect.

Main St.

Interior Sketch:



*Sewer line goes under
foundation (covered)
comes out near vent.*

Owner:	CVS.
Address:	25 Broadway Ave.
Phone Number:	
Date / Time:	Wed. 6/22/22.

potentail.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on grade.

No known drains

Some leadus
go into
ground.


No sump

Interior Sketch:

Owner:	
Address:	25 Broadway Ave.
Phone Number:	
Date / Time:	

East Main St.

Exterior Sketch:



Owner:	
Address:	25 Denison.
Phone Number:	
Date / Time:	Fri 6/24/22.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
Leads onto gr.
Sump to back yard.
Lat loc. inside.
Cleanout not found.

Denison


Interior Sketch:



Owner:	
Address:	25 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	25 Roosevelt Ave.
Phone Number:	
Date / Time:	Fri. 6/24/22.

potential



Contemporary Art Glass by Jeffrey Parr.
Glass Blowing Studio.

Angie's Pizza Restaurant.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on grade ✓

No leaders, 1 old not connected

Water coming up thru floor.

Interior Sketch:

Internal drains piped to
exter. towards storm sewer.

Internal drains not visible.

Glassblowing Studio
has separate sewer lat.

Sump pump in kitchen goes up to ceiling, could
not trace owner doesn't know where it discharges


ner:	Nick Salerno
ess:	26 Denison Ave
phone Number:	(860) 205-3461
Date / Time:	Wednesday, May 18 1 PM



GIS Link# = 174-12-2


Interior Inspection:

1. Lateral location: ✓
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? NA
3. Clean/clear water connections? NA. but well head in yard-hist
4. Sump Pump? Yes
 - a. Sewer? No
 - b. Storm/ground? Yes, see pictures
5. Floor Drains? No
6. Internal Roof Drains? No
7. Electric / Breaker Box ✓
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets Yes, all elevated ~4' 8 outlets



floor is stone

Interior Sketch:



Owner:	
Address:	26 Denison
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains *No*
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

*yes. around
rain garded / berm
built ~ 2009
perforated pipe
pic of trench
to dry well,*

2. Roof Leader Discharge

- a. Location ✓
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type) ✓
- b. Driveways (type) ✓
- c. Walkways (type) ✓
- d. Trees (4" and larger - size and type) ✓
- e. Shrubs / bushes ✓
- f. Landscaped areas *see sketch*
- g. Decks / Patios *Yes*
- h. Irrigation valves or sprinkler system *No*
- i. Bulkheads ✓
- j. Oil fill lines ✓
- k. Yard Drains ✓

4. Photos


- a. Front of building ✓
- b. Confirmed or suspected illicit connections
- c. Cleanout - if no illicit connections ✓

Owner:	
Address:	26 Denison Ave
Phone Number:	
Date / Time:	

drain (1/2 inch)
drain (1/2 inch)



Exterior Sketch:



Owner:	Steve Peglow
Address:	26 Main St. OM.
Phone Number:	
Date / Time:	Mon. 6/27/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
No illicit connect.


No sump.

No cleanout visible.

Leads onto gr.

last located

Interior Sketch:




Owner:	
Address:	26 Main St OM.
Phone Number:	
Date / Time:	



Exterior Sketch:

Main St.



Owner:	Joe Regan
Address:	27 Broadway Ave - Spa, offices, & apartments
Phone Number:	
Date / Time:	Monday 6/27/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement

2 sump pumps.


Lat located

Leads into ground.

No illicit connections.

~~Basement~~ Broadway Ave.

Interior Sketch:




Owner:	
Address:	27 Broadway Ave.
Phone Number:	
Date / Time:	



Exterior Sketch:

Broadway Ave



Owner:	Lauren Wills
Address:	27 Broadway Ave Ext.
Phone Number:	
Date / Time:	Wed. 6/22/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets




No gutters

Basement

2 sump pumps, yard discharge

No illicit connections


Interior Sketch:



Owner:	
Address:	27 Broadway Ave Ext.
Phone Number:	
Date / Time:	



Exterior Sketch:



potential.

Owner:	
Address:	28 Broadway Ave Ext.
Phone Number:	
Date / Time:	Wed. 6/22/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Vacant house.

No response

Notice still on doors

Windows to basement.

Leads into ground w/
black flex hose.


Could not locate clean out

Interior Sketch:

Owner:	
Address:	28 Broadway Ave Ext.
Phone Number:	
Date / Time:	



Exterior Sketch:




Owner:	Apple Rehab - Gary
Address:	28 Broadway Ave Ext
Phone Number:	(860) 536-9655
Date / Time:	Tuesday, May 17, 2022 2PM



GIS Link # = 174-21-5

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

Owner:	
Address:	Apple Rehab
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to


3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

MARY ELIZABETH NURSING CENTER EVACUATION ROUTES




Owner:	Apple Rehab - Gary
Address:	28 Broadway Ave Ext
Phone Number:	(860) 536-9655
Date / Time:	Tuesday, May 17, 2022 2PM



GIS Link # = 174-21-5

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

Owner:	
Address:	Apple Rehab
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains


4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	Apple Rehab
Phone Number:	
Date / Time:	



Exterior Sketch:




Swamp goes thru found
to dry well on property
see pic.

Roof runoff from
mastars is off
side of
see pic of
penetration

N

MARY ELIZABETH NURSING CENTER EVACUATION ROUTES



#3

Owner:	Mystic Pet Shop - Genevive
Address:	28 East Main St.
Phone Number:	(866) 572-4424
Date / Time:	Wed. 5/11/22 11AM

John



GIS Link # = 182-5-1

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains? *NA*
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Roof Leader 3**Interior Sketch:**

No basement
No crawl space.

Owner:	
Address:	Mystic Pet Shop
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type) *metal black*
 - b. Driveways (type) *white wood*
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	Mystic Pet Shop
Phone Number:	
Date / Time:	




Exterior Sketch:

No crawl space or basement

5 total roof leaders.

2BR



Willow St.

*S

Owner:	
Address:	28 Washington.
Phone Number:	
Date / Time:	Wed - 6/29/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Potential
→ sump into gr.

Resident left me on porch for 15 min. after answering door.

leads onto ground
not located

Did not do interior insp.

Sump pump discharge on side of house into ground.

storm sewer on street @ that corner, most likely sent there.


Interior Sketch:

Resident indicated they weren't sure who I was, land lord had no notification, I told him I would be back if needed.

He said sump pump is disconnected.

Owner:	
Address:	28 Washington.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	29 Broadway Ave Ext.
Phone Number:	
Date / Time:	Fri, 6/3/22 ~ 9:40 AM



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.

No illicit connections.


bulk head in back + interior access

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Josh Parsons
Address:	29 Main St. OM
Phone Number:	
Date / Time:	Wed. 6/8/22



Sound Real Estate Services-

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No basement.

No gutters

No sump


No illicit connections.

Interior Sketch:

Owner:	
Address:	29 Main St OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



#2

Owner:	Apple Rehab - Out Building
Address:	29 Washington
Phone Number:	(800)
Date / Time:	Ned, May 18 th , 2022 10 AM




GIS # = same as
Apple Rehab.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Lat
27" from FF
59" from ceiling

Interior Sketch:



Owner:	
Address:	29 Washington - Apple Rehab
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	29 Washington - Apple Rehab.
Phone Number:	
Date / Time:	



Exterior Sketch:



No roof leads.

Owner:	
Address:	30 Broadway Ave Ext
Phone Number:	
Date / Time:	Wed. 6/22/22.

potential.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Vacant house.

No response

Notice still on door.

Windows to basement.


Leads into ground w/ black flex hose.

Could not locate clean out

Interior Sketch:

Owner:	
Address:	30 Broadway Ave Ext.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Taguerio - Hot Tacos, Cdb Margaritas
Address:	30 Broadway
Phone Number:	
Date / Time:	Thurs 6/16/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No basement +
Slab on grade.

Leads onto gr.

No sump.

Interior Sketch:


No illicit connects

Could not locate sewer lat.

Owner:	
Address:	30 Broadway.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	30 Main St. OM.
Phone Number:	
Date / Time:	Tues. 6/28/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No external
Cleanout.
Crawl Space.
No sump.


Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	30 Washington
Phone Number:	
Date / Time:	Wed. 6/29/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Basement.

2 sump pumps
discharge outside.

leads onto ground.
No illicit connections.

Washington.

Interior Sketch:




Owner:	
Address:	30 Wash
Phone Number:	
Date / Time:	



Exterior Sketch:

Wash



Owner:	Paddy Hanse - St. Patrick's Church
Address:	31 E. Main St. build.
Phone Number:	
Date / Time:	Tues 6/14/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump discharges outside
Leads onto gr.
Lat located.

No illicit connections


31 is now part of 33+35
lots.

Interior Sketch:



Owner:	
Address:	31 E. Main St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Julianne Wagner (owner) —
Address:	31 Mistuxet
Phone Number:	(800) 501-1446
Date / Time:	Wednesday, May 18 9AM

Sara Homes
tenant




potentially but
unlikely

GIS Link # = 173-5-14

Interior Inspection:

1. Lateral location:
 - a. Horizontal ✓
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? Yes, capped
3. Clean/clear water connections? no
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground? ✓
5. Floor Drains? NO
6. Internal Roof Drains? NO
7. Electric / Breaker Box ✓
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



Owner:	
Address:	31 Mistuxet
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	31 Mistake
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Willow Properties.
Address:	31 Willow St.
Phone Number:	
Date / Time:	Mon. 6/27/22.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets Willow

Finished basement.
 1 leader into ground.
 rest on ground.
 No sump pump.



Interior Sketch:

finished lowest level.
 Could not locate lat inside.




lat area.

Owner:	
Address:	
Phone Number:	
Date / Time:	

4/11/11

Exterior Sketch:



Owner:	Structure being built.
Address:	32 Broadway.
Phone Number:	
Date / Time:	Fri. 6/24/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No basement.

Stilts.

No leadus.

No sump.

Interior Sketch:


Structure @ studs/frame.
 since it's new construction
 should meet code and won't
 be connected to sewer w/
 sump pump or roof leadus

No illicit connections

Owner:	
Address:	32 Broadway.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	32 Church.
Phone Number:	
Date / Time:	Wed. 6/22/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.

Lat loc.


No Sump.

Leads into ground.

Church.

No illicit connections


Interior Sketch:



Owner:	
Address:	32. Church St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	St. Patricks Rectory
Address:	32 Jackson Ave. East Main.
Phone Number:	
Date / Time:	Tues. 6/14/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

East Main.

Sump pump dis
to st-

Lat located

Leads into gr.


No illicit connections

Interior Sketch:

* ~1 month ago

31, 33, 35 was
combined to 1
address.

Based on GIS map this
is 1 address.



Owner:	
Address:	32 Main St. OM
Phone Number:	
Date / Time:	Sat. 7/2/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement window visible.

1 car in driveway.

Lat not located.


Potential sump pump discharge located.

Leads onto ground.

Interior Sketch:

Owner:	
Address:	32 Main St. OM.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Bill Coyle
Address:	32 Willow
Phone Number:	(860) 460-6998
Date / Time:	Wed 5/11/22




GIS Link = 182-4-8

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? *No*
3. Clean/clear water connections?
4. Sump Pump? *✓*
 - a. Sewer? *to sewer*
 - b. Storm/ground?
5. Floor Drains? *No*
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	David Shields.
Address:	33 Church St.
Phone Number:	
Date / Time:	Wed 6/29/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No external cleanout.

Lat located inside.

Sump discharges to lawn.

Leads onto ground except 1 into drywell?

Interior Sketch:




Church

Owner:	
Address:	33 Church St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Jim Fayal (tenant) - Jessica Rozzi-ochs
Address:	33 Main St, Old Mystic
Phone Number:	
Date / Time:	Tuesday, 6/7/22 9AM.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No Sump.

Minimal ~~lateral~~ leadus.

Basement gravel & shallow.

Main St.


Interior Sketch:



Owner:	
Address:	33 Main St, Old Mystic.
Phone Number:	
Date / Time:	

Main St.

Exterior Sketch:



potential - no sketch

Owner:	Fire Dept.
Address:	34 Broadway Ave.
Phone Number:	
Date / Time:	Thurs. 6/16/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on Grade

Lat. not located.

Leads go into ground.
→ storm drain system.
drains @ ^{truck} door's.

Interior Sketch:

A+ HQ.

Owner:	
Address:	Mobil Station - 34 East Main
Phone Number:	
Date / Time:	Wed. 6/15/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

No illicit connections.

Slab on grade.
Leadus discharge
to ground.


Owner of station not there.
Attend

[Kalim Malik
(800) 908-6213
left message. 6/15 @ 10:42

No sump.

Owner:	
Address:	34 East Main
Phone Number:	
Date / Time:	

Exterior Sketch:




Owner:	Ralph Howard Jr.
Address:	34 Main St. OM.
Phone Number:	
Date / Time:	Thurs. 6/23/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



Crawl space.

Sump discharges outside.

Leads onto gr.

No other drains.

No illicit connections

Could not locate cleanout.


Main St.



Owner:	
Address:	34 Main St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Paul Mandell
Address:	34 Washington
Phone Number:	(860) 424-7749
Date / Time:	Tues. 6/21/22



*potential.
very unlikely*

*Paul spoke w/ prev. owners
and indicated leaders & sump
discharged into back.*

4 leaders piped.


*Sump pump
to back yard (see pic)*

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Washington

Interior Sketch:




Owner:	
Address:	34 Washington.
Phone Number:	
Date / Time:	



Exterior Sketch:

Washington.

Discharges
to ditch in back



Owner:	
Address:	35 Main St. OM.
Phone Number:	
Date / Time:	Sat. 7/2/22.

potential.
no internal inspection



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

1 car in driveway.

No gutters.

Rear of house completely fenced in.

No sump pump discharge visible.


No cleanout visible.

No leaders

Owner:	
Address:	35 Main St. - 014
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Falk Eye Center.
Address:	35 Washington St. —
Phone Number:	
Date / Time:	Thursday, 6/16/22

potential - no sketch

Optometrist



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections.

Falk Eye Centers, LLC

No sump.
Leads into storm system.


lat located.

Leads.

Storm sewer.
Piping system tie into storm sewer.

Red valve from build to prevent backflow into property.


Interior Sketch:



Owner:	
Address:	35 Washington St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Glenn Cox
Address:	35 Willow St.
Phone Number:	
Date / Time:	Thurs. 6/9/22 9AM.

Sketch.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump pump tied into Sewer.

Drainage issues in yard, pooling etc.

2 sewer laterals.

Interior Sketch:



Owner:	
Address:	36 Church St.
Phone Number:	
Date / Time:	Fri. 6/24/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Crawl space.
Lat located.

No sumps.
No illicit connection.
Leads onto ground.

Interior Sketch:



Lat.

Church



~~potential~~

Owner:	
Address:	36 Denison -
Phone Number:	
Date / Time:	Thurs. 6/23/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Owner did not want me in the house.
has government issues -

Says he doesn't have a
sump pump, thinks WPCA
should take his word.

Interior Sketch:


Leads onto gr.

Last cleanout located.

Can't confirm sump pump.

Owner:	
Address:	36 Denison
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	36 Washington.
Phone Number:	
Date / Time:	Thurs. 6/16/22



Residence.

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump pump attached to sewer location.

Flooding issues.


lovely older gentleman

Interior Sketch:



Owner:	
Address:	300 Washington
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Glenn Cox.
Address:	37 Willow St.
Phone Number:	
Date / Time:	Wed. 6/15/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump.


Doesn't run.

Connected to sewer.

Crawl space.

~ 4' dirt floor.


Interior Sketch:



Owner:	
Address:	37 Willow St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	38 Church St.
Phone Number:	
Date / Time:	Wed. 6/22/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement


Leads onto gr.

Lat & cleanout located

No illicit connections

Church St.


Interior Sketch:



Owner:	
Address:	38 Church
Phone Number:	
Date / Time:	

Exterior Sketch:

Church



Owner:	Copper Beech.
Address:	38 East Main - Professional
Phone Number:	Building
Date / Time:	Wed. 6/15/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Stifel Investment
 Dr. Michael Sullo Fine Art Studio.
 Spark Wellness Acupuncture &
 Herbal Medicine.

No Sump.
 HVAC has PVC connections to
 exterior of build. see pics.

Basement

No illicit connections


Interior Sketch:



East Main.

Owner:	
Address:	38 E. Main - Copper Beech
Phone Number:	Prof. Build.
Date / Time:	

Exterior Sketch:



Owner:	
Address:	39 Denison.
Phone Number:	
Date / Time:	Thurs. 6/23/22

Sketch



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump tied into
sewer.


Leads into gr.



Basement.

6" d
CI.

Interior Sketch:




Denisen

Owner:	
Address:	39 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Denison.

[Signature]

Owner:	Cara
Address:	39 East Main - William Rave's
Phone Number:	
Date / Time:	Wed. 6/15/22 Tues. 6/21/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

left notice
in meeting 6/15


No illicit connect.

Crawl Space.

~~WASH.~~ E Main St.

Interior Sketch:


Confined space.
Recently treated w/
mold treatment so
I did not enter.



No sump

Drain in basement
tied to storm sewer.


Manual pump when
there's excessive flows.



Owner:	
Address:	39 E. Main
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Bob Mohr
Address:	39 Main St, Old Mystic
Phone Number:	(202) 256-4817
Date / Time:	Tues. 5/10/22

GIS Link = 166-3-9

#A



Holy Hock Farm Antiques.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


part old barn (southside)
part cmu block warehouse
painted white

Appointment was made
James didn't show-up or
answer phone.
Did exterior inspection.

Building is on a stream
roof leaders seem to go thru.
1 leader into ground.

→ N

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	40 Church St.
Phone Number:	
Date / Time:	Fri. 6/24/22.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.

Sump is manual.
never used.


Manual sump. Leads
onto ground.
→ never used.

Interior Sketch:



Owner:	
Address:	40 Church St.
Phone Number:	
Date / Time:	

Exterior Sketch:




Owner:	
Address:	40 Denison.
Phone Number:	
Date / Time:	Thurs. 6/23/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement




No Sump.

Lat was located inside, cleanout not vis. outside. (pave stones)

Denison.


Interior Sketch:



Leads into ground have perforated pipe for garden watering (see pic.)

Owner:	
Address:	40 Denrson.
Phone Number:	
Date / Time:	

Exterior Sketch:




Owner:	Bob & Elaine Boissevain
Address:	40 Holmes Street, N Stonington
Phone Number:	(860) 599-3551
Date / Time:	Tuesday, May 17 2022



GISLink # = 173-12-15

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? *No*
6. Internal Roof Drains?
7. Electric / Breaker Box *No*
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets *✓*

*have not used in 17 yrs**~20 outlets
all elevated**elevated lip for add'n
6" from floor***Interior Sketch:**

Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains *No*
- b. Patio Drains *No*
- c. Driveway Drains *No*
- d. Lawn Drains *No*
- e. Foundation Drains *No*

2. Roof Leader Discharge

- a. Location *✓*
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

No, from interior → *old ~~drain~~ cut*


4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	
Phone Number:	
Date / Time:	

4' Fence

Exterior Sketch:



GIS Link = 166-6-28 #5

Owner:	Anne Budding
Address:	40 Main Street, Old Mystic
Phone Number:	seahorse42aj@yahoo.com
Date / Time:	Tues, 5/10/22 2 PM.



Interior Inspection:


1. Lateral location:
 - a. Horizontal *Could not access*
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? *No*
3. Clean/clear water connections? *No*
4. Sump Pump? *Not visible.*
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? *NA*
6. Internal Roof Drains? *NA*
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible) – *pics*
8. Outlets *Not visible.*

Tenant name is Dave DeLucia

Colonial

Interior Sketch:

N



Owner:	
Address:	40 Main St, Old Mystic.
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains No
- b. Patio Drains No
- c. Driveway Drains No
- d. Lawn Drains No
- e. Foundation Drains No

2. Roof Leader Discharge

- a. Location back of house 2, to ground
- b. Discharge to I went into ground, appears to terminate - there

3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type) No
- b. Driveways (type) gravel
- c. Walkways (type) front of house
- d. Trees (4" and larger - size and type)
- e. Shrubs / bushes - see sketch
- f. Landscaped areas No
- g. Decks / Patios No
- h. Irrigation valves or sprinkler system No
- i. Bulkheads No
- j. Oil fill lines Yes - see sketch
- k. Yard Drains No

4. Photos

- a. Front of building ✓
- b. Confirmed or suspected illicit connections
- c. Cleanout - if no illicit connections basement / crawl space pic

Owner:	Anne Budding
Address:	40 Main St., Old Mystic
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	41 Denison.
Phone Number:	
Date / Time:	Thurs. 6/23/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.
lat located
Leads onto ground.

No illicit connect


Interior Sketch:



Owner:	
Address:	41 Denisen.
Phone Number:	
Date / Time:	

Exterior Sketch:

Denisen



Owner:	Laurie - Contry 21
Address:	41 E Main
Phone Number:	
Date / Time:	Wed - 6/15/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on Grade .
No basement
No sump .

Lat on driveway side .
no cleanout .

Interior Sketch:

Owner:	Willow.
Address:	41 Washington St.
Phone Number:	
Date / Time:	Tues 6/14/22.



Interior Inspection:

- Lateral location:
 - Horizontal
 - Vertical (to centerline) – beneath finished floor
- Additional sanitary connections?
- Clean/clear water connections?
- Sump Pump?
 - Sewer?
 - Storm/ground?
- Floor Drains?
- Internal Roof Drains?
- Electric / Breaker Box
 - Location
 - Amp capacity (if visible)
- Outlets

~~1 address~~ ^{address}, 2 buildings


Sump pump to yard.

~~Leads disconnected.~~ ^{under renovation}
~~looks like they disch. on ground~~

No illicit Connections.
 Leads into ground.

4 1/2" sewer sent to
 #41 for discharge to sewer

Interior Sketch:




Additional sink drain into ground
 near where the sewer last goes
 under foundation. near
 clean out.

Owner also owns 15 Washington
 very friendly.

Owner:	Willow
Address:	41 Washington St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	42 Church St
Phone Number:	
Date / Time:	Thursday 10/23/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement

No sump

Could not locate cleanout
Vent is capped inside.

No illicit connections

Church St


Interior Sketch:



Owner:	
Address:	42 Church St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	42 Denison
Phone Number:	
Date / Time:	Thurs. 6/23/22

~~XXXXXXXXXX~~ NA



Basement.

Manual sump pump
to yard.

Leads onto ground
grains beside driveway


No ill

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Interior Sketch:

Denison



Owner:	
Address:	42 Denison
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Anten.
Address:	43 Dennison St.
Phone Number:	
Date / Time:	Sat. 6/4/22 ~ 2PM.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit Connections.
No sketch.

Potential Illicit.


Basement.

Interior Sketch:



Owner:	
Address:	43 Dennison
Phone Number:	
Date / Time:	

Exterior Sketch:



Sump &
Roof leaders
go into piping in
back yard.
underground, not
visible.

Done construction
w/ this pipe.
-> resident verified.
not connected to
sewer.

Dennison.

Owner:	
Address:	44 Denison
Phone Number:	
Date / Time:	Thurs. 6/23/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

yellow house.


No sump.

1 leadu goes into
ground destination
is unknown

Denison.




Interior Sketch:



Owner:	
Address:	44 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	United Methodist Old Mystic Congregational Church
Address:	44 J Main St. PM
Phone Number:	
Date / Time:	Mon. 6/27/22.

potential
no response.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No internal inspection.

Leads onto ground.
1 leader into ground, looks
locally dry well.

No other discharges visible.


Interior Sketch:

Owner:	
Address:	44 Main St. OM.
Phone Number:	
Date / Time:	



Exterior Sketch:

Main St.



Owner:	Joe St Martin - Mystic Congregational Church
Address:	45 East Main Street
Phone Number:	(860) 271-1597
Date / Time:	Wednesday, May 18 11 AM



GIS Link # = 174-6-9.


Met @ 43 East Main St

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains? *No*
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

None of the other buildings had sump laterals

In room with point of entry not clear if pipes were not sealed to room but did not see a vent pipe to ext gr.



Interior Sketch:



Owner:	
Address:	Mystic Cong Church
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	Mystic Cong Church.
Phone Number:	
Date / Time:	

Exterior Sketch:




Town of Stonington

Geographic Information System (GIS)



Date Printed: 5/18/2022



MAP DISCLAIMER - NOTICE OF LIABILITY

This map is for assessment purposes only. It is not for legal description or conveyances. All information is subject to verification by any user. The Town of Stonington and its mapping contractors assume no legal responsibility for the information contained herein.

Approximate Scale: 1 inch = 40 feet




Owner:	Debbie
Address:	46-48 Main St. OM.
Phone Number:	
Date / Time:	Thursday 6/9/22 5:15 PM



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


Interior Sketch:



Owner:	
Address:	46-48 Main St. OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Old Mystic General Store.
Address:	47 Main St OM
Phone Number:	
Date / Time:	Saturday 7/2/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Slab on grade.

Lat not located


Leachus - 1 into gr.
near stream
most likely
discharged there.

Interior Sketch:

Owner:	
Address:	47 Main St. OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	48 Denison.
Phone Number:	
Date / Time:	Thurs. 6/23/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump discharges
out side (to drywell).


Lat located
Cleanout located.

No known illicit connect.

Leaders into ground.

- put pipe
- dry wells. on prop.

Interior Sketch:




Denison.

Owner:	
Address:	48 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Lawyers Office.
Address:	49-51 21 Main OM.
Phone Number:	
Date / Time:	Thurs 6/9/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No illicit connections

Property in disrepair
still an active law firm



Main St.


Interior Sketch:



Owner:	
Address:	49-51 111 Main St. OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Gretchen Kowal.
Address:	50 Church St.
Phone Number:	
Date / Time:	Sat. 7/2/22.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump tied into sewer.
(#1)
#2 to outside.
duplex.

Northwest
Connections

Church

Interior Sketch:




Sump #1 is a
booster for ww
for lower apartment.

Owner:	
Address:	50 Church St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Sketch

#3

Owner:	Kathi Murphy
Address:	51 Church Street
Phone Number:	(860) 599-1980
Date / Time:	Thursday, May 19 2 PM



GIS Link # = 174-9-14

Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump Pump

Apt #6

connected to sewer

Leads discharge onto ground
 Some go into gr. but
 discharge into drive thru pipe (see pics)
 or directly onto ground.

Interior Sketch:Apts.
#15-18

Owner:	
Address:	Murphy Prop. 51 Church St
Phone Number:	
Date / Time:	




External / Exterior Inspections:

1. Yard Drains
 - a. Window Drains
 - b. Patio Drains
 - c. Driveway Drains
 - d. Lawn Drains
 - e. Foundation Drains
2. Roof Leader Discharge
 - a. Location
 - b. Discharge to
3. Existing surface features from right-of-way + 10 feet from back of house
 - a. Fence (height & type)
 - b. Driveways (type)
 - c. Walkways (type)
 - d. Trees (4" and larger – size and type)
 - e. Shrubs / bushes
 - f. Landscaped areas
 - g. Decks / Patios
 - h. Irrigation valves or sprinkler system
 - i. Bulkheads
 - j. Oil fill lines
 - k. Yard Drains
4. Photos
 - a. Front of building
 - b. Confirmed or suspected illicit connections
 - c. Cleanout – if no illicit connections

Owner:	
Address:	Murphy Prop 51 Church St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	51 Washington.
Phone Number:	
Date / Time:	Tues. 6/21/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sump is tied into sewer.


Leads go into ground.
black flex hose.

appears to be discharged in yard.

Lat located on interior
could not find on exterior.



Interior Sketch:




Washington

Owner:	
Address:	51 Washington
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Debbie.
Address:	52 Main St. OM
Phone Number:	
Date / Time:	Thursday 6/9/22 5PM



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets



Main St.

Interior Sketch:

No clean out
or vent on exterior.




Halcy's
Way.

Owner:	
Address:	52 Main St OM.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	52 Wash.
Phone Number:	
Date / Time:	Tues 6/21/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Sump.
 Leads into gr.
 No illicit
 connections.


Wash

Interior Sketch:



Owner:	
Address:	52 Washington.
Phone Number:	
Date / Time:	

Exterior Sketch:



Washington.

Owner:	
Address:	53 Main St.
Phone Number:	
Date / Time:	Wed, 6/8/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No sump.

Lat. id'd.

leaders on to ground


sm. crawl space w/ lateral under porch.

Interior Sketch:



Owner:	
Address:	53 Main St OM
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	54 Church St.
Phone Number:	
Date / Time:	Tues - 6/28/22.

potential
(1 leader.)

HART CONSULTS
EXPERTISE IN WATER AND WASTE WATER SOLUTIONS, LLC.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.
Leads (various)
1 goes into gr.

→ N
Sump discharge to yard.


Interior Sketch:



Owner:	
Address:	54 Church St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	54 Denison.
Phone Number:	
Date / Time:	Fri. 6/24/22.



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
Sump discharged to yard.
Leads onto ground

No illicit connections
Lat located.

Denison.


Interior Sketch:



Owner:	
Address:	54 Denison.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	54 E. Main
Phone Number:	
Date / Time:	Tues 6/21/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

3 sump pumps
tied to storm sewer.

Leads onto ground
lot located.

No illicit
connections

Interior Sketch:




Owner:	
Address:	54 E Main.
Phone Number:	
Date / Time:	



Exterior Sketch:

E Main

~~Outlets~~ reconnected
to



#1

Owner:	Gwen Joseph
Address:	54 Washington Street
Phone Number:	(860) 536-1567
Date / Time:	Thursday, May 19 10 AM




GIS Link # = 174-16-5

Interior Inspection:

1. Lateral location: ✓
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? No
3. Clean/clear water connections?
4. Sump Pump? ✓
 - a. Sewer? No
 - b. Storm/ground? ✓
5. Floor Drains? No
6. Internal Roof Drains? No
7. Electric / Breaker Box ✓
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Sewer Lat
30" above fl
54" from ceiling

Outlets
elevated

Interior Sketch:

Owner:	
Address:	5A Washington Ave
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

NO

2. Roof Leader Discharge

- a. Location
- b. Discharge to



3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	54 Washington Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Dr. Beth Collins
Address:	55 Willow St
Phone Number:	(800) 572-6868
Date / Time:	Fri. 6/24/22



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets


No illicit connections

*Basement
Sump pump discharged
to wet lands
Lat located*


*Leads into ground
but discharged @ retaining
wall, rocks, and
drywell in
parking lot*

Willow St

Interior Sketch:




6" PVC



Owner:	
Address:	55 Willow Street.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Mike Lewis
Address:	56-58 East Main St
Phone Number:	
Date / Time:	Sat. 7/2/22.



No illicit connect.


56

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.
Lat loc. in & out.
Leads. onto ground.

Interior Sketch:



Owner:	Mike Lewis
Address:	56-58 E. Main St.
Phone Number:	
Date / Time:	Saturday 7/2/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connect.


Basement
Leads onto gr.
Lat line.

#58.




East Main.

Interior Sketch:



Owner:	
Address:	58 E. Main St.
Phone Number:	
Date / Time:	

Exterior Sketch:



Sketch

#5

Owner:	Anne (Buena Vista Real Estate)
Address:	56 Washington St.
Phone Number:	(860) 572-7305
Date / Time:	Tues. May 17, 2022 4pm

Access
myself
exterior
door
(yellow)




GIS Link # = 174-15-1

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



Washington

Owner:	
Address:	56 Washington
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	56 Washington
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Haley Smith.
Address:	57 Main Street OM.
Phone Number:	
Date / Time:	Thurs. 6/9/22 4:30 PM



No illicit connection.


No Sump.
Leads discharge onto ground.
Lat. located.
vent on exterior

Basement

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:



After

Owner:	
Address:	58 Main St OM.
Phone Number:	
Date / Time:	Wed. 6/8/22




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connect.
Leads onto gr.
Sump to yard.
Basement.

Main St.


Interior Sketch:



Owner:	
Address:	58 Main St.
Phone Number:	
Date / Time:	



Exterior Sketch:




Owner:	Anne (Buena Vista Real Estate)
Address:	58 Washington St.
Phone Number:	(860) 572-7305
Date / Time:	Tues. May 17, 2022 4pm

Glen




GISLink# = 174-15-10

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
 2. Additional sanitary connections?
 3. Clean/clear water connections?
 4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
 5. Floor Drains?
 6. Internal Roof Drains?
 7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
 8. Outlets
- 
- A hand-drawn sketch of a building footprint, likely a rectangular structure. The sketch includes several dimensions and labels. A horizontal dimension line at the top right is labeled '16''. A vertical dimension line on the right side is labeled '20''. A diagonal line from the top right corner towards the center is labeled '10''. There are several tick marks along the edges of the rectangle, possibly indicating specific locations or features. The sketch is drawn in a simple, hand-drawn style with black lines on a white background.

Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	58 Washington
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	59 East Main St.
Phone Number:	
Date / Time:	Tues. 6/21/22.




No illicit connect.
Leads on ground.
No sump.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:




E. Main

Owner:	
Address:	59 East Main.
Phone Number:	
Date / Time:	



Exterior Sketch:



#4

Owner:	Bill O'Donne II
Address:	60 Washington Street
Phone Number:	
Date / Time:	Thursday, May 19 4pm

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

GIS Link# = 174-15-9A

Residence.

No answer.

downstairs residents do not know Bill, upstairs did not respond.

Front Roof Leaders are plumbed into white PVC that go underground sump also.

Most likely to storm drain on road. Neighbor @ 62 Wash. has the same setup.

Owner:	
Address:	60 Washington
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

2. Roof Leader Discharge

- a. Location
- b. Discharge to

3. Existing surface features from right-of-way + 10 feet from back of house


- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	60 Washington
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	John Johnson.
Address:	Allen Spool Mill
Phone Number:	60 Willow.
Date / Time:	Tues, 8/28/22.



Lobby @ 10 AM.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Susan Agnion, (800) 884-9339
 John Johnson's Assistant
 (800) 235-3335 (John)
 Property Management Office
 (800) 447-8370.

No illicit connections

Interior Sketch:




Water 11

Owner:	The Allen Spool Mill
Address:	600 Willow St.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Kris & Heather Waters
Address:	61 East Main St, Mystic
Phone Number:	
Date / Time:	Tues, 5/10/22 4:00


GIS Link = 174-8-10

#6.




Interior Inspection:

1. Lateral location:
 - a. Horizontal ✓
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections? NO
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer? bath.
 - b. Storm/ground?
5. Floor Drains? NO
6. Internal Roof Drains? NO
7. Electric / Breaker Box ✓
 - a. Location ✓
 - b. Amp capacity (if visible)
8. Outlets ✓



Interior Sketch:



Owner:	
Address:	61 E Main St.
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains ✓
- b. Patio Drains ✓
- c. Driveway Drains ✓
- d. Lawn Drains ✓
- e. Foundation Drains ✓

2. Roof Leader Discharge

- a. Location
- b. Discharge to

See notes

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads *NO*
- j. Oil fill lines
- k. Yard Drains *NO*


4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	61 East Main
Phone Number:	
Date / Time:	

1890 historical Cape house.

Exterior Sketch:



Owner:	62 Main St OM.
Address:	400 Main St
Phone Number:	
Date / Time:	Saturday 7/2/22.




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.

Lat located
Leads onto gr.
Sump to back yard.
No illicit connex


Interior Sketch:



Owner:	62 Main St OM
Address:	48 Main St
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	62 Washington
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains
- b. Patio Drains
- c. Driveway Drains
- d. Lawn Drains
- e. Foundation Drains

NO

2. Roof Leader Discharge

- a. Location
- b. Discharge to



3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type)
- b. Driveways (type)
- c. Walkways (type)
- d. Trees (4" and larger – size and type)
- e. Shrubs / bushes
- f. Landscaped areas
- g. Decks / Patios
- h. Irrigation valves or sprinkler system
- i. Bulkheads
- j. Oil fill lines
- k. Yard Drains

NO door


4. Photos

- a. Front of building
- b. Confirmed or suspected illicit connections
- c. Cleanout – if no illicit connections

Owner:	
Address:	62 Washington
Phone Number:	
Date / Time:	1/1/2020



Exterior Sketch:



Owner:	Haley Smith
Address:	63 Main St. OM.
Phone Number:	
Date / Time:	Thurs. 6/9/22. 4:45





Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connection


Crawl Space.
No sump.
Leads onto ground.
let located.

Interior Sketch:



Owner:	
Address:	63 Main St OM:
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Don.
Address:	64 Washington.
Phone Number:	
Date / Time:	Mon - 6/27/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

1 side is dental practice
1 side is private residence.

Basement


No illicit connections

No sump in either building.

Dental sends Q to house for common discharge.

Dental has a booster pump for waste discharge.

Interior Sketch:




No sump pump in either building.

Washington St

Owner:	
Address:	64 Washington
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Richard,
Address:	68 Main St.
Phone Number:	
Date / Time:	Sat 7/2/22 Wed. 7/6/22.



Tues or 7/5 } around 12.
Wed. 7/6 }

Weekend visit 7/2/22.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Arranged time to come back. Wed. @ noon.

No show

No internal inspection.


Interior Sketch:

Owner:	Richard-
Address:	68 Main St.
Phone Number:	
Date / Time:	



Rental.
Wed. @ ~12.

Exterior Sketch:



Main St.

Owner:	
Address:	165 Whitehall
Phone Number:	
Date / Time:	Tues 6/28/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement.


No sump found.

Leads onto ground.

Lat found internal.

No illicit connect.


Interior Sketch:



Owner:	
Address:	165 Whitehall
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	175 Whitehall.
Phone Number:	
Date / Time:	Fri., 6/3/22. ~10:30 AM



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit connections

Lower level is garage.

No leadus
No sump pump.


Interior Sketch:



Owner:	
Address:	175 Whitehall.
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	195 Whitehall
Phone Number:	
Date / Time:	Wednesday - 6/29/22



Interior Inspection:


1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Basement
No sump
leads into ground.

⚡ No illicit connect.

White hall


Interior Sketch:




Owner:	
Address:	195 Whitehall
Phone Number:	
Date / Time:	



Exterior Sketch:



Whitehall



Owner:	Neri
Address:	196 Whitehall
Phone Number:	
Date / Time:	Tues. 6/28/22



potential
leader.

Basement

No Sump

Leads onto ground.

↓ into ground.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Whitehall!




Interior Sketch:



Owner:	
Address:	
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Liz Bialek
Address:	199 White Hall Ave, Mystic
Phone Number:	(860) 884-8165
Date / Time:	Tues. 5/10/22 5PM




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer? NO
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Whitehall
not
white hall

coming out of ground

Interior Sketch:



Owner:	
Address:	199 Whitehall
Phone Number:	
Date / Time:	



External / Exterior Inspections:

1. Yard Drains

- a. Window Drains *No*
- b. Patio Drains *No*
- c. Driveway Drains *No*
- d. Lawn Drains *No*
- e. Foundation Drains *No*

2. Roof Leader Discharge

- a. Location *marked on sketch*
- b. Discharge to *rear lawn - photo of discharge.*

3. Existing surface features from right-of-way + 10 feet from back of house

- a. Fence (height & type) *SE - 6' wood (along rd.)*
- b. Driveways (type) *stone*
- c. Walkways (type) *Na*
- d. Trees (4" and larger - size and type) *NA*
- e. Shrubs / bushes *Na*
- f. Landscaped areas
- g. Decks / Patios *rear, see sketch*
- h. Irrigation valves or sprinkler system
- i. Bulkheads *No, doors on exterior to access basement*
- j. Oil fill lines *✓*
- k. Yard Drains *No*


4. Photos

- a. Front of building *✓*
- b. Confirmed or suspected illicit connections *No*
- c. Cleanout - if no illicit connections *✓*

Owner:	
Address:	199 Whitehall
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	
Address:	201 Whitehall
Phone Number:	
Date / Time:	Fri, 6/3/22. ~ 2:30




Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No illicit Connections.
No Sump pump

Interior Sketch:




Owner:	
Address:	201 Whitehall,
Phone Number:	
Date / Time:	



Exterior Sketch:

Drinking Water Well here.



Owner:	
Address:	207 Whitehall Ave.
Phone Number:	
Date / Time:	Sat. 7/2/22

potential.



no response.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Rental Property.

3 cars in driveway
knocked on 3 doors

no response.

Interior Sketch:


No apparent sump discharge
Lat located – cleanout,

hatch in lawn.

All leaders go into
ground.

Owner:	
Address:	207 Whitehall Ave.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	Josh Lyons
Address:	1437 Pequot Trail
Phone Number:	(860) 961-6087
Date / Time:	Tues. 6/21/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Lat located.

No sump.


Leads onto gr.

No sump pump

Confirmed


No illicit connections

Interior Sketch:



Owner:	
Address:	1437 Pegnot Trail
Phone Number:	
Date / Time:	

Exterior Sketch:



Pegnot Trail

Owner:	
Address:	1440 Peguot Trail
Phone Number:	
Date / Time:	Wed. 7/6/22



Scott. Donovan.

(860) 234-8829.

Must Do, LLC.

scott@gdoran.com.

scb sent email.

potential.

No internal inspection.


Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Interior Sketch:

Owner:	
Address:	1440 Pequot Trail.
Phone Number:	
Date / Time:	

Exterior Sketch:



Owner:	
Address:	1443 Pequot.
Phone Number:	
Date / Time:	Tues. 6/7/22.


No sketch - potential illicit
 • garage drain
 • leaders in to gr.
HART CONSULTS
 EXPERTISE IN WATER AND WASTEWATER SOLUTIONS, LLC.

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No Sump.
 Floor drain in garage.
 Leaders into ground.


Interior Sketch:



Owner:	
Address:	1443 Pequod
Phone Number:	
Date / Time:	



Exterior Sketch:



Owner:	Pam.
Address:	1444 Pequot Trail
Phone Number:	
Date / Time:	Tues 6/14/22.



Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

No sketch.


Isaac Morgan } historic
Cabinetmaker } house.
1832

Dry well in front yard.
1 leader goes into it.

Sump pump in basement
sent to exterior drains
in yard.

Lat. located but whole pipe
not visible.

Interior Sketch:



Pequot Trail.

Owner:	
Address:	1446 Pegnot Trail
Phone Number:	
Date / Time:	Tues - 6/28



*potential.
1 leaders
into gr-*


*Basement
Leads into ground.
No sump pump.
No drains.*

Interior Inspection:

1. Lateral location:
 - a. Horizontal
 - b. Vertical (to centerline) – beneath finished floor
2. Additional sanitary connections?
3. Clean/clear water connections?
4. Sump Pump?
 - a. Sewer?
 - b. Storm/ground?
5. Floor Drains?
6. Internal Roof Drains?
7. Electric / Breaker Box
 - a. Location
 - b. Amp capacity (if visible)
8. Outlets

Pegnot Trail.

Interior Sketch:



Owner:	
Address:	1446 Regent.
Phone Number:	
Date / Time:	

Exterior Sketch:

